

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22009169/AGNCM4**Date:** 16/11/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002176805
Claimant Vehicle No :	SJZ9281R	Insured Vehicle No :	SGN3547S
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	285312

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ9281R	Engine No:	HR12276962B
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Chassis No:	JN1TAAE12Z0980174
Reg. Date:	19/01/2018 (Man. Year: 2017)	Odometer:	123974 km
Colour:	Red		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,172.22	7,591.75	2,580.47	25.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	2,460.00	1,410.00	36.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,042.22	10,051.75	3,990.47	28.42
Approved Total (Overridden) (\$\$)		8,000.00		
(\$\$)	14,042.22	8,000.00	6,042.22	43.03
+ GST 7.00/7.00% (\$\$)	982.96	560.00	422.96	43.03
Nett Amount (\$\$)	15,025.18	8,560.00	6,465.18	43.03

INSPECTION

Date of Assignment:	19/09/2022	Mirage Motorwerkz Pte Ltd (HQ)
Date Inspected:	19/09/2022 Inspected At:	10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE
Estimated Period of Repair:	8.0 days	Singapore 417868

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2022)
Parts:	144	NISSAN NOTE 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ9281R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	485.90 FL	*485.90 FL
2	1		*FRONT BUMPER SIDE HOLDER	O/s Damaged	58.00 FL	*28.50 FL
3	1		*FRONT BUMPER TOW COVER	Not Necessary	24.90 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	381.60 FL	*381.60 FL
5	1		*FRONT BUMPER SPONGE	Cracked	218.60 FL	*218.60 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	71.50 FL	*- FL
7	1		*FRONT BUMPER UNDERCOVER	Deformed	225.60 FL	*225.60 FL
8	1		*FRONT GRILLE	Cracked	328.90 FL	*328.90 FL
9	1		*FRONT GRILLE LOGO	Necessary	64.90 FL	*64.90 FL
10	1		*FRONT GRILLE TOP COVER	Missing	304.40 FL	*304.40 FL
11	2		*HEADLAMP	Cracked	3,229.20 FL	*3,229.20 FL
12	1		*FRONT SUPPORT PANEL	Buckled	485.20 FL	*485.20 FL
13	1		*AIR CON CONDENSER	Warped	658.20 FL	*658.20 FL
14	2		*AIR CON CONDENSER SIDE GUIDE	Deformed	90.60 FL	*90.60 FL
15	1		*RADIATOR	Not Necessary	689.60 FL	*- FL
16	1		*ENGINE MOUNTING RH	Torn	258.90 FL	*258.90 FL
17	1		*ENGINE MOUNTING FRONT	Torn	287.50 FL	*287.50 FL
18	1		*FRONT RH FENDER	Repair	554.00 FL	*- FL
19	1		*FRONT RH FENDER INNER SHIELD	Torn	158.90 FL	*158.90 FL
20	1		*FRONT RH SHOCK ABSORBER	Not Necessary	373.20 FL	*- FL
21	1		*FRONT RH LOWER ARM	Bent	285.90 FL	*285.90 FL
22	1		*FRONT RH KNUCKLE ARM	Not Necessary	435.60 FL	*- FL
23	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	264.70 FL	*264.70 FL
24	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
25	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
26	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
29	1		*BOT COOLANT	Necessary	50.00 FS	*40.00 FS
30	1		*SET FRONT GRILLE TOP COVER CLIPS	Necessary	30.00 FS	*20.00 FS
31	1		*SET AIR CON CONDENSER SIDE GUIDE CLIPS	Necessary	20.00 FS	*20.00 FS
32	1		*FRONT RH WHEEL RIM	Cut	680.00 FS	*450.00 FS
33	1		*FRONT RH TYRE	Not Necessary	280.00 FS	*- FS
					Sub Total (\$)	11,165.80
					- List Item Discount on L Items 10.00/10.00% (\$)	993.58
					Total Parts (\$)	10,172.22
						8,367.50
						775.75
						7,591.75

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAY PAINTING	New	800.00	600.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	100.00	80.00
5	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	New	120.00	60.00
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	New	120.00	60.00
7	TO LIFT UP ENGINE TO FACILITATE REPAIRS	New	500.00	350.00
8	TO REPAIR & STRAIGHTEN CHASSIS MEMBERS	New	480.00	350.00
9	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	150.00
10	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			3,870.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >