

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009170/RVCQ2**Date:** 01/02/2023**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00265002100

**Claimant Vehicle No :** SMX5719Y**Insured Vehicle No :** SLM5376Y

Date of Loss: 09/09/2022

Nature of Claim: TP

Claim No: SNM22D206455/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMX5719Y**

Make &amp; Model: TOYOTA NOAH, 1.8 (A)

Engine No: 2ZR2G40744

Reg. Date: 20/01/2021 (Man. Year: 2019)

Chassis No: ZWR800428316

Colour: Maroon

Odometer: 155157 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,591.49	3,370.91	5,220.58	60.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,460.00	1,210.00	45.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,261.49</b>	<b>4,830.91</b>	<b>6,430.58</b>	<b>57.10</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,850.00</b>		
<b>(\$\$)</b>	11,261.49	3,850.00	7,411.49	65.81
<b>+ GST 8.00/8.00% (\$\$)</b>	900.92	308.00	592.92	65.81
<b>Nett Amount (\$\$)</b>	<b>12,162.41</b>	<b>4,158.00</b>	<b>8,004.41</b>	<b>65.81</b>

**INSPECTION**

Date of Assignment: 16/09/2022

Date Inspected: 19/09/2022 Inspected At:

My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ)  
60 Jalan Lam Huat, Carros Centre #05-21  
Singapore 737869

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX5719Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	798.20 FL	*798.20 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	324.40 FL	*- FL
3	1		*TAILGATE	Buckled	2,110.25 FL	*1,812.00 FL
4	1		*TAILGATE INNER TRIM	Not Necessary	589.00 FL	*- FL
5	1		*TAILGATE HYBRID SYNERGY DRIVE LOGO	Necessary	141.10 FL	*141.10 FL
6	1		*TAILGATE WEATHERSTRIPE	Necessary	391.05 FL	*391.05 FL
7	1		*TAILGATE LOCK	Not Necessary	512.00 FL	*- FL
8	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	387.00 FL	*181.00 FL
9	1		*TAILGATE DETECTOR	Not Necessary	287.00 FL	*- FL
10	1		*TAILGATE BUZZER	Not Necessary	198.00 FL	*- FL
11	1		*REAR END PANEL	Bent	689.20 FL	*689.20 FL
12	1		*REAR END PANEL TOP GARNISH	Cracked	391.45 FL	*242.00 FL
13	1		*REAR FLOOR PANEL	Not Necessary	2,489.00 FL	*- FL
14	1		*SET REAR FLOOR PANEL TOP BOARD	Not Necessary	1,241.00 FL	*- FL
15	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
16	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
17	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
18	1		*TAILGATE WINDSCREEN SEALANT }	Necessary	80.00 FS	*60.00 FS
19	1		*TAILGATE WINDSCREEN INNER SEAL }	Necessary	80.00 FS	*- FS
20	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
22	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
					Sub Total (S\$)	11,228.65      4,434.55
					- List Item Discount on L Items 25.00/25.00% (S\$)	2,637.16      1,063.64
					Total Parts (S\$)	8,591.49      3,370.91

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
2	REMOVE AND REFIT REAR SEAT ,UPHOLTERY	New	300.00	0.00
3	REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	40.00
4	REMOVE AND REFIT TAILGATE MECHANISM	New	150.00	60.00
5	TO CHECK ELECTRICAL WIRING	New	200.00	0.00
6	TUFF COAT	New	150.00	40.00
7	PANEL BEATING ON AFFECTED AREA	New	800.00	600.00
8	SPRAY ON AFFECTED AREA	New	800.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,670.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >