



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 7501B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PAIR FRONT FORK ASSY	BENT	1,100.00	1,100.00
1	SET BATTERY	NOT NECESSARY	54.00	-
1	SET RH FRONT FOOTREST	BROKEN	45.00	45.00
1	SET L/R MIRROR	CUT	70.00	70.00
1	SET L/R TANK COVER	DEFORMED	180.00	180.00
	LESS 10% DISCOUNT		-	-139.50
			1,449.00	1,255.50
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	LABOUR CHARGE.		120.00	120.00
			170.00	170.00
	GRAND TOTAL		1,619.00	1,425.50
RECOMMENDED COST OF REPAIRS				1,425.50

Report Ref No. CS3/LPC22005709/Tvy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.