



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 9168T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER (MATT) (CONSISTENT)	BROKEN	175.00	152.00
1	FRONT FORK ASSY (CONSISTENT)	BENT / TWISTED	980.00	780.00
1	FORK UNDER BRACKET (CONSISTENT)	BENT	190.00	190.00
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	550.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	180.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	52.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	48.00	-
1	FRONT SIDE COVER (1 SET) -MATT (CONSISTENT)	CUT	260.00	150.00
1	FRONT SIDE INNER COVER -MATT (CONSISTENT)	CUT	210.00	150.00
1	FRONT LOWER COVER (CONSISTENT)	TORN	195.00	148.00
1	FUEL TANK COVER (CONSISTENT)	CRACKED	105.00	105.00
1	HEADLAMP (LED) (CONSISTENT)	CRACKED	980.00	699.00
1	SET SIDE MIRROR (CONSISTENT)	CUT	120.00	60.00
1	HANDLE -BAR (CONSISTENT)	BENT	165.00	165.00
1	HANDLE -BAR BALANCER (N/S) (CONSISTENT)	CUT	115.00	30.00
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	60.00	-
2	BRAKE LEVER (CONSISTENT)	N/S CUT	110.00	55.00
2	FOOTSTEP PANEL (CONSISTENT)	N/S CUT	510.00	138.00
2	FOOTSTEP PANEL LOWER COVER (CONSISTENT)	N/S CUT	340.00	135.00
1	EXHAUST ASSY (CONSISTENT)	NOT NECESSARY	680.00	-
1	EXHAUST PROTECTOR (CONSISTENT)	NOT NECESSARY	48.00	-
1	SET FAIRING COVER (CONSISTENT)	CRACKED	1,450.00	900.00
1	REAR FOOTREST (N/S) (CUT)	NOT CONSISTENT WITH THE IMPACT	180.00	-
	LESS 10% DISCOUNT		-770.30	-385.70
			6,932.70	3,471.30
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	38.00	-
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NECESSARY	120.00	68.00

Report Ref No. CC4/ASM22009177/Upa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX (SN) (CONSISTENT)	NOT NECESSARY	480.00	-
1	REAR BOX BRACKET (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
1	SET STICKER (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	'AEROX' EMBLEM (SN) (CONSISTENT)	NECESSARY	60.00	60.00
			1,084.00	128.00
	<b>LABOUR</b>			
	TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME .	NOT NECESSARY	380.00	-
	TO PROVIDE LABOUR.		450.00	300.00
			910.00	300.00
<b>GRAND TOTAL</b>			<b>8,926.70</b>	<b>3,899.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,100.00</b>

Report Ref No. CC4/ASM22009177/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.