

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22009178/EYA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070122144
Claimant Vehicle No :	SMR3702P	Insured Vehicle No :	SKZ8500D
Date of Loss:	15/09/2022	Nature of Claim:	TP
		Claim No:	0137828328SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3702P		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK088187
Reg. Date:	31/12/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF54KA079221
Colour:	Blue	Odometer:	25478 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,743.00	13,215.28	6,527.72	33.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,372.00	3,022.00	2,350.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	25,115.00	16,237.28	8,877.72	35.35
+ GST 8.00/8.00% (\$\$)	2,009.20	1,298.98	710.22	35.35
Nett Amount (\$\$)	27,124.20	17,536.26	9,587.94	35.35
+ Loss of Use (5.0 x S\$90.00/day) (\$\$)		450.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		17,988.26		

INSPECTION

Date of Assignment:	23/09/2022	
Date Inspected:	23/09/2022	Inspected At: Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,493.00 FS	*1,994.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Broken	254.00 FS	*203.20 FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	72.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Missing	529.00 FS	*423.20 FS
8	1		*RADIATOR GRILLE	Cut	2,576.00 FS	*2,060.80 FS
9	2		*FRONT PARKING AID SENSOR SUPPORT -LH/RH	Not Necessary	116.00 FS	*- FS
10	1		*FRONT PARKING AID SENSOR -OUTER	Not Necessary	266.00 FS	*- FS
11	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
14	1		*FRONT WHEEL SPOILER -RH	Broken	82.00 FS	*65.12 FS
15	1		*FRONT SPOILER -RH	Crushed	40.00 FS	*32.00 FS
16	1		*FRONT FENDER -RH	Dented	1,189.00 FS	*951.20 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
18	1		*FRONT FENDER CLOSING ELEMENT -RH	Bent	83.00 FS	*65.84 FS
19	1		*FRONT FENDER BRACKET -RH	Bent	65.00 FS	*32.72 FS
20	2		*FRONT FENDER BRACKET -LH/RH	Not Necessary	79.00 FS	*- FS
21	1		*FRONT FENDER BRACE -RH	Bent	132.00 FS	*105.20 FS
22	5		*FRONT FENDER RIVET	Necessary	19.00 FS	*15.20 FS
23	1		*FRONT FENDER LEDGE COVER -RH SHORT	Necessary	18.00 FS	*13.92 FS
24	1		*FRONT FENDER LEDGE COVER -RH LONG	Necessary	40.00 FS	*31.44 FS
25	1		*FRONT WHEEL HOUSING LINER -RH	Crushed	299.00 FS	*238.80 FS
26	1		*FRONT BUMPER GUIDE SECTION -RH	Broken	41.00 FS	*32.24 FS
27	1		*FRONT FENDER STONE CHUP GUARD	Not Necessary	57.00 FS	*- FS
28	1		*FRONT FENDER CHROME TRIM -RH	Necessary	171.00 FS	*136.40 FS
29	1		*HEADLIGHT -RH	Cut	8,416.00 FS	*6,732.80 FS
30	1		*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
31	1		*SUNDRIES	Necessary	300.00 FS	*20.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

19,743.00

13,215.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,900.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,372.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >