

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009183/TYA3Q2**Date:** 13/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000064
Claimant Vehicle No :	SGW4461Y	Insured Vehicle No :	GBK4421K
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	8534009082SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW4461Y		
Make & Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Engine No:	8ARZ104358
Reg. Date:	26/01/2018 (Man. Year: 2017)	Chassis No:	JTEZB3GH60J001111
Colour:	White	Odometer:	49245 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,055.92	1,876.80	2,179.12	53.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	660.00	890.00	57.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,605.92	2,536.80	3,069.12	54.75
+ GST 7.00/7.00% (S\$)	392.41	177.58	214.83	54.75
Nett Amount (S\$)	5,998.33	2,714.38	3,283.95	54.75
+ Car Rental (3.0 x S\$130.00/day) (S\$)		390.00		
Nett Liability (S\$)		3,104.38		

INSPECTION

Date of Assignment:	27/09/2022		
Date Inspected:	27/09/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent	1,650.00 FL	*1,650.00 FL
2	1		*REAR RH DOOR LOWER CHROME PROTECTOR }	Cracked	185.00 FL	*185.00 FL
3	1		*REAR RH DOOR WINDOW GLASS CHROME GARNISH }		0.00 FL	*- FL
4	1		*REAR RH DOOR TRIM BOARD	Not Necessary	1,180.00 FL	*- FL
5	1		*REAR RH DOOR HINGE -UPPER	Repair	17.00 FL	*- FL
6	1		*REAR RH DOOR HINGE -LOWER	Repair	81.20 FL	*- FL
7	1		*REAR RH DOOR POWER WINDOW REGULATOR MOTOR	Not Necessary	996.60 FL	*- FL
8	1		*REAR RH DOOR POWER WINDOW REGULATOR	Not Necessary	210.00 FL	*- FL
9	1		*REAR RH DOOR WEATHERSTRIP RUBBER	Not Necessary	181.60 FL	*- FL
10	1		*REAR RH DOOR CHECK	Not Necessary	239.10 FL	*- FL
11	1		*REAR RH DOOR LOCK	Bent	667.40 FL	*667.40 FL
Sub Total (\$\$)						5,407.90 2,502.40
- List Item Discount on L Items 25.00/25.00% (\$\$)						1,351.98 625.60
Total Parts (\$\$)						4,055.92 1,876.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	600.00	250.00
2	CHECK WIRING FUNCTIONS TRANSFER DOOR FITTING	New	150.00	60.00
3	PUTTY ,APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS	New	800.00	350.00
Gross Labour Cost (S\$)			1,550.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >