



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 3020Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TOP BOX (SN)	NOT NECESSARY	300.00	-
1	HANDPHONE MOUNT (SN)	TO REPAIR SEE LABOUR	20.00	-
1	MIRROR COMP R,BACK (SN)	CUT	90.59	90.59
1	PIPE, STEERING HANDLE (SN)	BENT	79.50	79.50
1	WEIGHT, STRG HNDL (SN)	CUT	5.49	5.49
1	WEIGHT B, STRG HND (SN)	NECESSARY	7.60	7.60
1	RUBBER A HANDLE (SN)	NECESSARY	2.50	2.50
1	NUT, SET 6MM (SN)	NECESSARY	5.10	5.10
1	LEVER ASSY, R HNDL (SN)	CUT	55.28	55.28
1	SET ILLUS, FR FEND (SN)	CUT	246.30	246.30
1	WINKER ASSY, R FRONT (SN)	CRACKED	151.30	151.30
1	PEDAL COMP, RR BRAKE (SN)	CUT	23.30	23.30
1	TANK ASSY, FUEL (SN)	DENTED	1,025.00	1,025.00
1	PACKING, BASE (SN)	NECESSARY	21.30	21.30
1	COVER ASSY, R FR S (SN)	CUT	16.43	16.43
1	COVER A,R SIDE (SN)	CUT	46.90	46.90
1	COVER B ASSY, R SI (SN)	CUT	24.75	24.75
1	SET ILLUS, L MIDDLE (SN)	CRACKED	270.60	270.60
1	SET ILLUSTRATE "TYPE2" (SN)	CUT	112.70	112.70
1	COWL B.R SIDE COWL (SN)	CUT	12.30	12.30
1	COVER COMP, RIGHT CRANKCASE (SN)	CUT	104.60	104.60
1	O RING 48.1X3.6 (SN)	NECESSARY	2.80	2.80
1	ORING 183 (SN)	NECESSARY	3.50	3.50
1	MUFFLER COMP (SN)	DENTED	564.70	564.70
1	COVER, MUFFLER (SN)	CUT	92.80	92.80
1	BOLT, FLANGE DR 8X (SN)	NECESSARY	0.90	0.90
1	LIGHT ASSY, HEAD (SN)	CUT	568.00	568.00
			3,854.24	3,534.24

Report Ref No. CS/TP22009189/Gvy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	TOWING FROM 8B ADMIRALTY TO BSS (RECEIPT NO. 10702).		45.00	45.00
	TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT, REALIGN AFFECTED PORTION TO ALIGNMENT. INCLUSIVE OF THE REPAIR OF HANDPHONE MOUNT.		1,050.00	700.00
	USING HONDA MOTORCYCLE COMMUNICATION SYSTEM (MCS) TO ERASE / RESET MEMORY.	NOT NECESSARY	120.00	-
			1,215.00	745.00
	<b>GRAND TOTAL</b>		<b>5,069.24</b>	<b>4,279.24</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,279.24</b>

Report Ref No. CS/TP22009189/Gvy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.