10/6/22, 5:03 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22009201/UVCQ2 Our File No:

06/10/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00051962200

TP

**Claimant Vehicle** No:

GBJ9329S

Insured Vehicle No:

YQ6801E

Date of Loss: 17/09/2022

Nature of

Claim:

Claim

SNM22D206646/C02/KHONGLH

JTFHT02P000249684

Yes

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**GBJ9329S** Reg No:

TOYOTA HIACE, 3.0 D TURBO 5DR (M) Make & Model:

Engine No: 1KDB013335

Reg. Date: 10/10/2019 (Man. Year: 2019)

Chassis No:

Odometer: 54977 km

Colour: Silver **Engine Capacity:** 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Rear Left Side: Yokohama 6 mm Bridgestone 6 mm Front Right Side: Rear Right Side: Bridgestone 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,190.62	1,386.90	9,803.72	87.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	640.00	3,520.00	84.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	\$) 15,350.62	2,026.90	13,323.72	86.80
Approved Total (Overridden) (S	\$)	1,600.00		
Nett Amount (S	\$) 15,350.62	1,600.00	13,750.62	89.58

**INSPECTION** 

Date of Assignment: 19/09/2022

Nineteen Autowerks Pte Ltd - Woodlands (HQ) Date Inspected: 20/09/2022 Inspected At: 39 Woodlands Close, MEGA@Woodlands #01-24

Singapore 737856

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

		_			
ட	$\sim$		ro	<b>n</b>	ce
$\boldsymbol{L}$	_	_	_		

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Oct 2022)

Parts: TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0) 213

Labour: Repairer's (Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for GBJ9329S)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	906.00 FL	*681.10 FL
2	4		*REAR BUMPER LOWER BRACKET	Not Necessary	180.40 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	132.20 FL	*- FL
4	1		*REAR BUMPER STEP PANEL	Not Necessary	299.80 FL	*- FL
5	2		*REAR BUMPER STEP TOP COVER L/R	Not Necessary	79.60 FL	*- FL
6	1		*REAR END PANEL (INNER)	Not Necessary	820.70 FL	*- FL
7	1		*REAR END PANEL (OUTER)	Repair	743.00 FL	*- FL
8	1		*REAR END PANEL L	Not Necessary	315.20 FL	*- FL
9	1		*REAR END PANEL R	Not Necessary	315.20 FL	*- FL
10	2		*REAR END PANEL SIDE RUBBER STOPPER L/R	Not Necessary	136.20 FL	*- FL
11	1		*REAR TAILGATE	Repair	2,265.00 FL	*- FL
12	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	71.60 FL	*- FL
13	1		*REAR TAILGATE TOYOTA HIACE STICKER	Not Necessary	58.00 FL	*- FL
14	1		*REAR SPARE TYRE CARRIAGE BRACKET	Not Necessary	243.10 FL	*- FL
15	1		*REAR SPARE TYRE CARRIAGE SCREW	Not Necessary	68.30 FL	*- FL
16	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	70.20 FL	*- FL
17	1		*REAR TAILGATE MECHANISM LOCK	Not Necessary	263.00 FL	*- FL
18	1		*REAR TAILGATE MECHANISM LOCK COVER	Not Necessary	136.00 FL	*- FL
19	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	387.60 FL	*- FL
20	1		*REAR TAILGATE WINDSCREEN SEAL	No such part	100.00 FL	*- FL
21	1		*REAR TAILGATE GLASS	Shorted	1,250.00 FL	*1,048.10 FL
22	1		*REAR TAILLAMP LH	Not Necessary	404.50 FL	*- FL
23	1		*REAR TAILLAMP LH	Not Necessary	404.50 FL	*- FL
24	1		*REAR TAILLAMP LOWER GARNISH RH	Not Necessary	155.00 FL	*- FL
25	1		*REAR TAILLAMP LOWER GARNISH LH	Not Necessary	155.00 FL	*- FL
26	2		*REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R	Not Necessary	106.00 FL	*- FL
27	1		*REAR FLOOR BOARD PANEL	Not Necessary	2,381.40 FL	*- FL
28	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
30	1		*REAR TAILGATE 70KM STICKER	Not Necessary	25.00 FS	*- FS
31	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*REAR TAILGATE WINDSCREEN SOLAR FILM	Not fitted	400.00 FS	*- FS
34	1		*REAR TAILGATE WINDSCREEN LALAMOVE STICKER	Not fitted	450.00 FS	*- FS
35	1		*REAR WOODEN FLOOR BOARD PANEL	Not Necessary	550.00 FS	*- FS
F=Fra	anchise	part. S=Spo	cNett. L=ListItemDisc.	•	,	

**Sub Total (S\$) 14,302.50** 1,819.20 432.30 - List Item Discount on L Items 25.00/25.00% (S\$) 3,111.88

> Total Parts (S\$) 11,190.62 1,386.90

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	20.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET	New	250.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	200.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,000.00	300.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	0.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	0.00
	Gross Labour Cost (S\$)		4,160.00	640.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >