

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009203/UNY3Q2**Date:** 07/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00026702200

Claimant Vehicle No : XE2341S **Insured Vehicle No :** XD2240E

Date of Loss: 06/09/2022 Nature of Claim: TP Claim No: SNM22D206650/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE2341S**

Make & Model: MITSUBISHI FUSO, 12.9 D FP51 (M) Engine No: OM457LA457972C0329645

Reg. Date: 20/10/2016 (Man. Year: 2016) Chassis No: FV51SJA20072

Colour: White Odometer: 362912 km

Engine Capacity: 11967 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: KPATOS 6 mm Rear Left Side: Ceat 6/6/6 mm

Front Right Side: KPATOS 6 mm Rear Right Side: Ceat 6/6/6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,442.07	3,338.30	17,103.77	83.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,270.00	1,180.00	4,090.00	77.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,712.07	4,518.30	21,193.77	82.43
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	25,712.07	3,600.00	22,112.07	86.00
+ GST 7.00/7.00% (S\$)	1,799.84	252.00	1,547.84	86.00
Nett Amount (S\$)	27,511.91	3,852.00	23,659.91	86.00

INSPECTION

Date of Assignment: 03/10/2022

Date Inspected: 21/09/2022 Inspected At: Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Oct 2022)	
Parts:	N/A	MITSUBISHI FUSO 12.9 D FP51 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE2341S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Not Necessary	5,177.32 FL	*- FL
2	1		*FRONT PANEL HANDLE RH	Not Necessary	150.11 FL	*- FL
3	1		*FRONT PANEL HINGE RH	Not Necessary	113.21 FL	*- FL
4	1		*FRONT PANEL ABSORBER RH	Not Necessary	565.68 FL	*- FL
5	1		*TOP GRILLE	Repair	521.79 FL	*- FL
6	1		*LOWER GRILLE	Not Necessary	727.97 FL	*- FL
7	1		*MITSUBISHI LOGO	Not Necessary	195.95 FL	*- FL
8	1		*FRONT CORNER PANEL RH	Cracked	468.21 FL	*468.21 FL
9	1		*FRONT CORNER PANEL BOTTOM BRACKET RH	Not Necessary	107.00 FL	*- FL
10	1		*FRONT CORNER PANEL CENTRE BRACKET RH	Bent	32.78 FL	*32.78 FL
11	1		*FRONT CORNER PANEL SIGNAL LAMP RH	Cracked	195.03 FL	*195.03 FL
12	1		*FRONT BUMPER	Repair	2,259.31 FL	*- FL
13	1		*FRONT BUMPER SIDE	Twisted	140.29 FL	*140.29 FL
14	1		*FRONT CENTRE BUMPER PANEL	Twisted	273.12 FL	*273.12 FL
15	1		*FRONT CENTRE BUMPER REINFORCEMENT	Not Necessary	884.79 FL	*- FL
16	1		*FRONT CENTRE SIDE BUMPER PANEL RH	Not Necessary	193.04 FL	*- FL
17	1		*FRONT CENTRE SIDE BUMPER REINFORCEMENT RH	Not Necessary	226.06 FL	*- FL
18	1		*HEADLAMP ASSY RH	Not Necessary	1,286.45 FL	*- FL
19	1		*HEADLAMP RIM RH	Not Necessary	181.18 FL	*- FL
20	1		*HEADLAMP ALUMINIUM BRACKET RH	Not Necessary	947.63 FL	*- FL
21	1		*FOG LAMP ASSY RH	Not Necessary	293.25 FL	*- FL
22	1		*FOG LAMP RIM RH	Not Necessary	186.05 FL	*- FL
23	1		*STEP PANEL UPPER RH	Not Necessary	324.55 FL	*- FL
24	1		*STEP PANEL LOWER RH	Not Necessary	270.56 FL	*- FL
25	1		*STEP PANEL UNDER COVER RH	Not Necessary	229.87 FL	*- FL
26	1		*STEP ALLOY MAT RH	Not Necessary	326.00 FL	*- FL
27	1		*STAND PANEL RH	Not Necessary	744.59 FL	*- FL
28	1		*STAND PANEL SIDE BRACKET RH	Not Necessary	754.70 FL	*- FL
29	1		*STAND PANEL ALLOY MAT -UPPER RH	Not Necessary	324.55 FL	*- FL
30	1		*STAND PANEL ALLOY MAT -LOWER RH	Not Necessary	289.84 FL	*- FL
31	1		*FRONT STEP PANEL BRACKET RH	Not Necessary	875.91 FL	*- FL
32	1		*REAR STEP PANEL BRACKET RH	Not Necessary	629.25 FL	*- FL
33	1		*FRONT DOOR ASSY RH	Distorted / Cracked	3,092.64 FL	*3,092.64 FL
34	1		*FRONT DOOR PILLAR RH	Repair	2,284.45 FL	*- FL
35	1		*FRONT DOOR INNER PILLAR RH	Repair	895.78 FL	*- FL
36	1		*FRONT DOOR INNER PILLAR GARNISH RH	Not Necessary	269.84 FL	*- FL
37	1		*FRONT DOOR HINGE UPPER RH	Not Necessary	227.77 FL	*- FL
38	1		*FRONT DOOR HINGE LOWER RH	Not Necessary	227.77 FL	*- FL
39	1		*FRONT DOOR SIGNAL LAMP RH	Broken	361.81 FL	*249.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	27,256.10	4,451.07
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,814.03	1,112.77
Total Parts (\$\$)	20,442.07	3,338.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT FRONT DOOR RH ,REALIGNMENT ,ETC }	New	120.00	600.00
2	LABOUR REMOVE & REFIT HEADLAMP BRACKET ,GARNISH & TO CHECK WIRING & REFOCUS ALL LIGHT }	New	100.00	0.00
3	LABOUR CHARGE TO CUT & WELD & DISMANTLE & REMOVE & REFIT ALL ABOVE PARTS }	New	2,300.00	0.00
4	TO SPRAY & PAINTING ALL ACCIDENT AFFECTED AREA	New	1,800.00	550.00
5	TO RUST PROOFING ON AFFECTED AREA	New	950.00	30.00
Gross Labour Cost (\$)			5,270.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >