

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22009204/KPA3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_02

Claimant Vehicle No : SMT9885U **Insured Vehicle No :** SMR8386K

Date of Loss: 18/09/2022 Nature of Claim: TP Claim No: MFL2022D0005260

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT9885U**
 Make & Model: TOYOTA VIOS, 1.5 G (A) Engine No: 2NRX434152
 Reg. Date: 12/04/2019 (Man. Year: 2019) Chassis No: MR2B23F3101172112
 Colour: Metallic Red Odometer: 71414 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,532.60	6,245.57	4,287.03	40.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	2,260.00	970.00	30.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,762.60	8,505.57	5,257.03	38.20
+ GST 7.00/7.00% (S\$)	963.38	595.39	367.99	38.20
Nett Amount (S\$)	14,725.98	9,100.96	5,625.02	38.20
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,008.41		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment: 19/09/2022

Date Inspected: 20/09/2022 Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2022)
Parts:	143	TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT9885U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	852.90 FL	*826.40 FL
2	1		*BOOT LID RUBBER	Distorted / Dented	190.10 FL	*190.10 FL
3	1		*BOOT LID INNER LOCK	Dented	432.50 FL	*432.50 FL
4	2		*BOOT LID HINGE	Repair	142.40 FL	*- FL
5	2		*BOOT LID LAMP	Cracked	893.80 FL	*893.80 FL
6	2		*BOOT LID LICENSE PLATE LAMP	Serviceable	141.60 FL	*- FL
7	1		*BOOT LID NO PLATE LAMP COVER	Distorted	165.20 FL	*165.20 FL
8	1		*BOOT LID INNER TRIM COVER	Deformed	352.00 FL	*352.00 FL
9	1		*BOOT LID LOGO	Necessary	66.90 FL	*66.90 FL
10	1		*BOOT LID VIOS EMBLEM	Necessary	49.40 FL	*49.40 FL
11	1		*BOOT LID G EMBLEM	Necessary	38.40 FL	*38.40 FL
12	1		*BOOT LID PRESS OPEN SENSOR	Serviceable	148.10 FL	*- FL
13	2		*TAILLAMP	N/S Cut / O/S Cracked	1,375.80 FL	*1,352.40 FL
14	2		*TAILLAMP SIDE CLIP	Necessary (1 PCS ONLY)	9.80 FL	*4.90 FL
15	1		*REAR END PANEL	Bent	803.20 FL	*781.10 FL
16	1		*END PANEL TOP GARNISH	Distorted	301.50 FL	*295.60 FL
17	1		*TAILLAMP CORNER PANEL	O/S Bent	256.40 FL	*128.20 FL
18	2		*REAR FENDER	Repair	1,961.60 FL	*- FL
19	2		*REAR FENDER INNER TRIM COVER	Deformed	712.80 FL	*712.80 FL
20	1		*SPARE TYRE PANEL	Repair	755.10 FL	*- FL
21	2		*SPARE TYRE PANEL SIDE PANEL	Repair	303.40 FL	*- FL
22	1		*SPARE TYRE BOARD	Dented / Cracked	329.60 FL	*329.60 FL
23	2		*SPARE TYRE BOARD SIDE PAD	O/S Buckled / N/S Distorted	182.40 FL	*182.40 FL
24	1		*SPARE TYRE NUT & SCREW	Serviceable	33.50 FL	*- FL
25	1		*REAR ANTENEL SENSOR	Serviceable	144.20 FL	*- FL
26	1		*REAR BUMPER FASCIA	Bent	570.90 FL	*557.70 FL
27	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	335.80 FL	*167.90 FL
28	1		*REAR BUMPER REINFORCEMENT	Repair	360.10 FL	*- FL
29	1		*REAR BUMPER REFLECTOR	O/S Missing	203.60 FL	*101.80 FL
30	2		*REAR BUMPER SIDE SEAL	Serviceable	157.40 FL	*- FL
31	1		*REAR EXHAUST SILENCER BOX	Repair	721.40 FL	*- FL
32	1		*REAR W/S GLASS SEALANT	Not Necessary	60.00 FS	*- FS
33	1		*REAR NO .PLATE WITH BOX	Bent	50.00 FS	*45.00 FS
34	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
35	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	300.00 FS	*200.00 FS
36	1		*REAR REVERSE CAMERA	Shorted	300.00 FS	*200.00 FS
37	1		*O/S TAILLAMP LOWER BRACKET	Cracked	65.00 FL	*65.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **13,796.80** **8,169.10**
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,264.20 1,923.53

Total Parts (\$\$) **10,532.60** **6,245.57**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	0.00
2	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	100.00
3	TO APPLY UNDERSEALING	New	100.00	60.00
4	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	60.00	0.00
5	TO PUTTY AND SPRAY REPLACED PARTS	New	1,300.00	1,200.00
6	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,500.00	900.00
Gross Labour Cost (\$\$)			3,230.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >