

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009221/UVY3Q2**Date:** 16/03/2023REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00104282203

**Claimant Vehicle No :** SGT8298S **Insured Vehicle No :** EJ928L

Date of Loss: 10/09/2022 Nature of Claim: TP Claim No: SNM22D206529/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGT8298S**

Make & Model: M.G. ZS EV, (A) Engine No: HIDDEN

Reg. Date: 26/04/2021 (Man. Year: 2021) Chassis No: LSJW74093MZ102341

Colour: Blue Odometer: 24211 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,594.65	3,864.15	730.50	15.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,840.00	3,530.00	5,310.00	60.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,434.65</b>	<b>7,394.15</b>	<b>6,040.50</b>	<b>44.96</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>940.43</b>	<b>517.59</b>	<b>422.84</b>	<b>44.96</b>
<b>Nett Amount (S\$)</b>	<b>14,375.08</b>	<b>7,911.74</b>	<b>6,463.34</b>	<b>44.96</b>

INSPECTION

Date of Assignment: 19/09/2022

Date Inspected: 26/09/2022 Inspected At: Trans Eurokars Pte Ltd (Ubi)  
5 Ubi Close  
Singapore 408605

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
<b>Parts:</b> M1-SUV	M.G. ZS EV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGT8298S)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	550.00 F	*550.00 F
2	1		*REAR BUMPER LOWER	Deformed	265.00 F	*265.00 F
3	1		*SPOILER REAR BUMPER LOWER	Deformed / Warped	380.00 F	*380.00 F
4	6		*FASTENER	Necessary	5.40 F	*5.40 F
5	5		*RIVET	Necessary	11.00 F	*11.00 F
6	1		*RETAINER S.S ULTRASONIC CENTER	Necessary	12.90 F	*12.90 F
7	1		*RETAINER S.S ULTRASONIC LH	Necessary	12.90 F	*12.90 F
8	1		*RETAINER S.S ULTRASONIC RH	Necessary	12.90 F	*12.90 F
9	1		*RETAINER LH REAR	Not Necessary	38.00 F	*- F
10	1		*RETAINER RH REAR	Not Necessary	38.00 F	*- F
11	1		*REAR REINFORCEMENT	Dented	380.00 F	*380.00 F
12	1		*COVER TOWING HOOK REAR	Deformed	11.00 F	*11.00 F
13	1		*LAMP LICENSE PLATE	Not Necessary	36.30 F	*- F
14	3		*SENSOR ULTRASONIC REAR	Serviceable	465.00 F	*- F
15	1		*TAILGATE	Badly Dented	1,900.00 F	*1,900.00 F
16	1		*TAILGATE LOCK	Serviceable	119.70 F	*- F
17	1		*COVER TAILGATE LOCK	Not Necessary	3.50 F	*- F
18	3		*GROMMET SCREW	Necessary	3.00 F	*3.00 F
19	1		*LOGO MG TAILGATE OPENER	Necessary	84.80 F	*84.80 F
20	1		*EMBLEM ZS EV	Necessary	25.25 F	*25.25 F
21	1		*SEALER ON THE WINDSCREEN GLASS	Necessary	120.00 FS	*120.00 FS
22	1		*NUMBER PLATE	Bent	70.00 FS	*70.00 FS
23	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>4,594.65</b>	<b>3,864.15</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND TAILGATE TO REPAIR REAR END PANEL	New	3,960.00	1,320.00
2	TO RESPRAY REAR BUMPER ,TAILGATE AND REAR END PANEL	New	2,400.00	1,260.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
4	TO TRANSFER TAILGATE MECHANISM	New	330.00	0.00
5	TO TRANSFER REVERSE SENSORS	New	660.00	120.00
6	TO RECHARGE THE CAR	New	165.00	0.00
7	FOR CARRYING OUT THE CHECKS ,VERIFYING AND DISABLING CONNECTION OF POWER (HV OR 12V) BEFORE REPAIR AND CHECKING RECONNECTION OF POWER AFTER REPAIR	New	165.00	0.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	120.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	150.00
10	TO CARRY -OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOU)	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>8,840.00</b>	<b>3,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >