

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22009225/RVY3M4**Date:** 20/03/2023**REFERENCE**

Insured/Claimant:	LOW LE MING	Policy No:	MPC21P00262200	
Date of Loss:	10/09/2022	Nature of Claim:	OD	Claim No: DMPC2200411H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD8658Z	Engine No:	R18A3010092
Make & Model:	HONDA CROSSROAD, 1.8 (A)	Chassis No:	RT11007494
Reg. Date:	20/06/2008 (Man. Year: 2008)	Odometer:	185031 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	S\$11,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,659.90	11,194.50	1,465.40	11.58
Miscellaneous Items	908.13	102.50	805.63	88.71
Labour	1,710.00	1,100.00	610.00	35.67
Paintwork Labour	800.00	600.00	200.00	25.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,078.03	12,997.00	3,081.03	19.16
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	16,078.03	8,000.00	8,078.03	50.24

INSPECTION

Date of Assignment:	19/09/2022 Present Location:	Zhong Cheng Enterprise Pte Ltd - Woodlands (HQ) 60 JALAN LAM HUAT #04-53 CARROS CENTRE SINGAPORE 737869
Date Inspected:	20/09/2022 Inspected At:	REPAIRER: ZHONG CHENG ENTERPRISE PTE LTD
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD8658Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Air-cond condenser (WCP)	Bent	580.00 F	*580.00 F
2	1		Bonnet (WCP)	Buckled	560.00 F	*560.00 F
3	1		Bonnet lock (WCP)	Bent	80.00 F	*80.00 F
4	1		Bumper air grille center, front (WCP)	Cracked	320.00 F	*320.00 F
5	1		Bumper bracket LH, front (WCP)	Necessary	40.00 F	*40.00 F
6	1		Bumper bracket RH, front (WCP)	Necessary	40.00 F	*40.00 F
7	1		Bumper reinforcement, front (WCP)	Bent	220.00 F	*220.00 F
8	1		Bumper, front (WCP)	Deformed	800.00 F	*800.00 F
9	1		Fender bracket LH, front (WCP)	Not Necessary	12.00 F	*- F
10	1		Fender bracket RH, front (WCP)	Not Necessary	12.00 F	*- F
11	1		Fender LH, front (WCP)	Not Necessary	500.00 F	*- F
12	1		Fender RH, front (WCP)	Not Necessary	500.00 F	*- F
13	1		Headlamp LH (WCP)	Cracked	740.00 F	*740.00 F
14	1		Headlamp RH (WCP)	Cracked	740.00 F	*740.00 F
15	1		Panel, front (WCP)	Bent	650.00 F	*650.00 F
16	1		Radiator (WCP)	Bent	900.00 F	*900.00 F
17	1		W/screen glass moulding upper, front (should be W/screen glass, front) (WCP)	Cracked	1,100.00 F	*1,100.00 F
18	1		W/screen glass, front (should be W/screen glass moulding upper, front) (WCP)	Necessary	95.00 F	*95.00 F
19	1		*carplate & housing	Bent	60.00 F	*35.00 FS
20	1		*front grille Honda logo emblem (WCP)	Necessary	50.00 F	*50.00 F
21	1		*radiator cowl (WCP)	Not Necessary	280.00 F	*- F
22	1		*AIR BAG CONTROL MODULE (WCP)	Activated	550.00 F	*550.00 F
23	1		*AIR BAG ASSY-PASSENGER (WCP)	Activated	880.00 F	*880.00 F
Supplementary #1						
24	1		*transmission gearbox assy (WCP)	Cracked	1,500.00 F	*1,500.00 F
25	1		Engine mounting, front (WCP)	Cracked	300.00 F	*300.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)

11,509.00

10,180.00

+ Margin on L,N Items 10.00/10.00% (\$\$)

1,150.90

1,014.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (\$\$)					12,659.90	11,194.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	aircon gas (NECESSARY)	30.00	30.00
2	1	gst	679.63	0.00
3	1	top up coolant (NECESSARY)	30.00	30.00
4	1	Windscreen sealant, front (NECESSARY)	42.50	42.50
Supplementary #1				
5	1	GST	126.00	-
Sub Total (S\$)			908.13	102.50

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	spray paint & polish	New	800.00	600.00
Labour Items				
2	panel beating /dismantle/refix front portions	New	800.00	600.00
3	dismantle/refix airbag and dashboard	New	450.00	200.00
4	radiator & condenser fixing	New	160.00	100.00
5	remove fault code	New	200.00	100.00
6	dismantle & refix windscreen	New	100.00	100.00
Gross Labour Cost (S\$)			2,510.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >