

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22009226/KQY3E2**Date:** 15/06/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001977784
Claimant Vehicle No :	SLN8385X	Insured Vehicle No :	FBR2989R
Date of Loss:	17/09/2022	Nature of Claim:	TP
		Claim No:	285412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8385X	Engine No:	2ZRR937983
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW506050567
Reg. Date:	18/05/2017 (Man. Year: 2016)	Odometer:	392773 km
Colour:	Metallic Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goform 9 mm	Rear Left Side:	Goform 9 mm
Front Right Side:	Goform 9 mm	Rear Right Side:	Goform 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,384.80	4,838.47	4,546.33	48.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,315.00	1,120.00	1,195.00	51.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,699.80	5,958.47	5,741.33	49.07
Approved Total (Overridden) (\$\$)		4,550.00		
(\$\$)	11,699.80	4,550.00	7,149.80	61.11
+ GST 8.00/8.00% (\$\$)	935.98	364.00	571.98	61.11
Nett Amount (\$\$)	12,635.78	4,914.00	7,721.78	61.11

INSPECTION

Date of Assignment:	20/09/2022		
Date Inspected:	20/09/2022	Inspected At:	Autoworx House 176 Sin Ming Drive #02-01 Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2023)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8385X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Bent	766.50 FL	*766.50 FL
2	1		*FRONT FENDER EMBLEM HYBRID	Necessary	76.80 FL	*76.80 FL
3	1		*FRONT FENDER DUST COVER	Cracked	264.30 FL	*198.40 FL
4	8		*FRONT FENDER DUST COVER CLIP	Necessary	28.80 FL	*28.80 FL
5	1		*FRONT BUMPER	Buckled / Cracked	967.80 FL	*593.10 FL
6	1		*FRONT BUMPER SIDE RETAINER	Distorted	76.40 FL	*76.40 FL
7	1		*FRONT HEAD LAMP	Cut	2,165.40 FL	*1,555.10 FL
8	1		*ALLOY RIM	Dented	690.00 FL	*690.00 FL
9	1		*FRONT KNUCKLE ARM	Bent	565.40 FL	*410.60 FL
10	1		*FRONT WHEEL BEARING	Necessary	316.50 FL	*- FL
11	1		*FRONT SHOCK ABSORBER	Bent	567.10 FL	*460.80 FL
12	1		*FRONT LOWER ARM	Distorted	367.30 FL	*367.30 FL
13	1		*FRONT STEERING TIE ROD	Serviceable	116.50 FL	*- FL
14	1		*FRONT STEERING TIE ROD END	Serviceable	162.70 FL	*- FL
15	1		*FRONT LOWER ARM BALL JOINT	Bent	196.40 FL	*196.40 FL
16	1		*FRONT ANTI ROLL BAR LINKAGE	Serviceable	188.50 FL	*- FL
17	1		*FRONT BUMPER UPPER REINFORCEMENT	Not Necessary	651.40 FL	*- FL
18	1		*FRONT BUMPER SPONGE ABSORBER	Cracked	546.30 FL	*155.20 FL
19	1		*FRONT BUMPER FOG LAMP	Mtg Cracked	667.10 FL	*588.90 FL
20	1		*FRONT BUMPER LOWER REINFORCEMENT (BENT)	Not Consistent With The Impact	540.00 FL	*- FL
21	1		*FRONT BUMPER LOWER REINFORCEMENT BRACKET (BENT)	Not Consistent With The Impact	295.00 FL	*- FL
22	1		*FRONT BUMPER LOWER REINFORCEMENT PAD	Serviceable	441.00 FL	*- FL
23	1		*WINDSCREEN WIPER WASHER TANK	Dented	394.30 FL	*287.00 FL
24	1		*SIDE MIRROR ASSY	Serviceable	679.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,731.00	6,451.30
- List Item Discount on L Items 20.00/25.00% (\$\$)	2,346.20	1,612.83
Total Parts (\$\$)	9,384.80	4,838.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	1,000.00	400.00
2	TO CHECK WIRING SYSTEM	New	60.00	20.00
3	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
4	TO CHANGE THE ALLOY RIM	New	40.00	20.00
5	TO CHECK THE WHEEL ALIGNMENT	New	85.00	60.00
6	TO CHANGE THE FRONT RH UNDER CARRIAGE	New	250.00	200.00
7	TO REMOVE & REPLACE FRONT WHEEL BEARING	New	80.00	20.00
Gross Labour Cost (\$\$)			2,315.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >