

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009231/UYA3Q2**Date:** 14/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100501130
Claimant Vehicle No :	SMU2040G	Insured Vehicle No :	SLL1631S
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	4994480500SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU2040G		
Make & Model:	MAZDA CX-5, 2.0 PREMIUM 2WD I2 (A)	Engine No:	PE31407086
Reg. Date:	30/07/2020 (Man. Year: 2019)	Chassis No:	JM6KF2W7AK0337441
Colour:	Brown	Odometer:	25633 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,138.80	4,241.20	4,897.60	53.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,650.00	1,810.00	52.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,598.80	5,891.20	6,707.60	53.24
+ GST 7.00/7.00% (S\$)	881.92	412.38	469.54	53.24
Nett Amount (S\$)	13,480.72	6,303.58	7,177.14	53.24
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,705.58		

INSPECTION

Date of Assignment:	20/09/2022	
Date Inspected:	20/09/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,650.00 FL	*2,200.00 FL
2	1		*TAILGATE LOGO	Not Necessary	90.00 FL	*- FL
3	1		*TAILGATE EMBLEM	Necessary	88.00 FL	*88.00 FL
4	1		*TAILGATE EMBLEM - SKYACTIV	Necessary	105.00 FL	*105.00 FL
5	1		*TAILGATE LOCK	Not Necessary	1,180.00 FL	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Not Necessary	614.00 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD SMALL COVER	Not Necessary	65.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Twisted	268.00 FL	*268.00 FL
9	1		*TAILGATE GARNISH	Repair	750.00 FL	*- FL
10	1		*REAR BUMPER	Dented	1,480.00 FL	*1,279.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Not Necessary	260.00 FL	*- FL
12	2		*REAR BUMPER CENTER BRACKET	Not Necessary	130.00 FL	*- FL
13	2		*REAR BUMPER REFLECTOR	Not Necessary	780.00 FL	*- FL
14	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	45.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Dented	720.00 FL	*682.00 FL
16	1		*REAR END PANEL	Repair	780.00 FL	*- FL
17	1		*REAR END PANEL GARNISH - TOP	Not Necessary	195.00 FL	*- FL
18	1		*TAILGATE GLASS MOULDING	Necessary	186.00 FL	*142.00 FL
19	10		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
20	10		*REAR BUMPER LOWER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*250.00 FS
22	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*SET REAR BUMPER RIVET	Necessary	50.00 FS	*50.00 FS
24	10		*TAILGATE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
25	10		*TAILGATE LOWER PROTECTOR CLIP	Not Necessary	50.00 FS	*- FS
26	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
27	1		*REAR END PANEL BODY SEALANT	Not Necessary	50.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
29	1		*TAILGATE GLASS INNER SEAL	Necessary	80.00 FS	*40.00 FS
30	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,216.00	5,194.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,077.20	952.80
Total Parts (\$\$)	9,138.80	4,241.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER TAILGATE DOOR PART	New	120.00	60.00
2	TRANSFER TAILGATE GLASS	New	120.00	120.00
3	TO CHECK NECESSARY WIRING	New	60.00	20.00
4	TO FIT REVERSE SENSOR	New	60.00	50.00
5	TO RUST PROOF PANELS	New	150.00	30.00
6	RE-INITIALISE POWER TAILGATE	New	300.00	60.00
7	TO REMOVE INNER TRIM, GARNISH, ETC TO FACILITE REPAIR AND TO FIX BACK	New	250.00	80.00
8	TO APPLY BODY SEALANT ON BODY JOINTS	New	200.00	0.00
9	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD REAR END PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	1,200.00	550.00
10	TO PUTTY AND SPRAY PAINT ON DAMAGE AFFECTED AREA	New	1,000.00	680.00
Gross Labour Cost (S\$)			3,460.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >