

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22009232/UNY3Q2**Date:** 05/10/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SGZ9555L**Insured Vehicle No :** GBK5554D

Date of Loss: 14/09/2022

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGZ9555L**

Make & Model: TOYOTA C-HR, 1.8 (A)

Engine No: 2ZR8111806

Reg. Date: 12/07/2017 (Man. Year: 2017)

Chassis No: ZYX102041335

Colour: White

Odometer: 149050 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18

Rear Tyre Size: 225/45Z R18

Front Left Side: Tourador 7 mm

Rear Left Side: Tourador 7 mm

Front Right Side: Tourador 7 mm

Rear Right Side: Tourador 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,456.53	5,639.19	5,817.34	50.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,630.00	1,200.00	42.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,286.53	7,269.19	7,017.34	49.12
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	14,286.53	5,800.00	8,486.53	59.40
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 20/09/2022

Date Inspected: 20/09/2022 Inspected At:

1 KAKI BUKIT ROAD AVE 6 #02-47

AUTOBAY@KB

Repairer: Jc Motors Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
Parts:	M1-SUV	TOYOTA C-HR 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ9555L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	1,806.23 FL	*1,806.23 FL
2	1		*TAILGATE GLASS	Not Necessary	1,260.92 FL	*- FL
3	1		*SET TAILGATE GLASS MOULDING	Necessary	201.12 FL	*201.12 FL
4	1		*TAILGATE LOGO	Necessary	126.55 FL	*126.55 FL
5	1		*TAILGATE EMBLEM CHR	Necessary	89.95 FL	*89.95 FL
6	1		*TAILGATE EMBLEM HYBRID	Necessary	91.50 FL	*91.50 FL
7	1		*TAILGATE LICENCE PLATE GARNISH	Cracked	1,233.45 FL	*1,233.45 FL
8	1		*TAILGATE INNER LOCK	Shorted	509.89 FL	*509.89 FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	481.93 FL	*- FL
10	1		*TAILGATE W/STRIP	Not Necessary	311.43 FL	*- FL
11	2		*TAILGATE LAMPS -L/R	Cracked	843.20 FL	*843.20 FL
12	2		*TAILLAMP -L/R	Not Necessary	1,373.00 FL	*- FL
13	1		*REAR BUMPER	Deformed / Torn	1,263.50 FL	*545.10 FL
14	1		*REAR BUMPER TOW COVER	Not Necessary	48.55 FL	*- FL
15	1		*REAR BUMPER DIFUSSER	Distorted	609.43 FL	*388.90 FL
16	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	1,212.48 FL	*606.24 FL
17	2		*REAR BUMPER REFLECTORS	Not Necessary	252.40 FL	*- FL
18	2		*REAR BUMPER SIDE COVERS	Not Necessary	363.80 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	690.23 FL	*690.23 FL
20	2		*REAR BUMPER SIDE RETAINER -L/R	Necessary	179.90 FL	*179.90 FL
21	1		*REAR END PANEL	Repair	760.95 FL	*- FL
22	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	181.20 FL	*- FL
23	2		*REAR LICENCE LAMPS	Not Necessary	137.10 FL	*- FL
24	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
25	1		*SET TAILGATE LICENCE GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
26	1		*REAR BUMPER TOP STEP RUBBER	Necessary	280.00 FS	*40.00 FS
27	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
28	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,963.71	7,467.26
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,507.18	1,828.07
Total Parts (\$\$)	11,456.53	5,639.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
3	TO RESPRAY UNDERCOATING	New	80.00	30.00
4	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	60.00
5	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
6	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
7	PANEL BEATING ,CUT,WELD ,REMOVE & REPLACING ABOVE PARTS	New	1,050.00	520.00
Gross Labour Cost (\$)			2,830.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >