

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009234/TVY3Q2**Date:** 28/03/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00263922101	
Claimant Vehicle No :	SKG3090C	Insured Vehicle No :	SMR3413Z	
Date of Loss:	18/09/2022	Nature of Claim:	TP	Claim No: SNM22D206691/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG3090C		Engine No:	CJE077656
Make & Model:	AUDI A4, 2.0 (A)		Chassis No:	WAUZZZ8K7EA122201
Reg. Date:	30/06/2014 (Man. Year: 2014)		Odometer:	152981 km
Colour:	Black			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,339.80	12,785.10	9,554.70	42.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,620.00	920.00	36.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,879.80	14,405.10	10,474.70	42.10
Approved Total (Overridden) (S\$)		11,500.00		
Nett Amount (S\$)	24,879.80	11,500.00	13,379.80	53.78

INSPECTION

Date of Assignment:	20/09/2022	PROMPT AUTO SOLUTIONS PTE LTD (Premier) 8 KAKI BUKIT AVE 4, #02-37 PREMIER@KAKI BUKIT Singapore 415875
Date Inspected:	20/09/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts: 143	AUDI A4 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKG3090C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	2,890.00 FL	*2,361.00 FL
2	2		*FRONT BONNET HINGE LH+RH	Not Necessary	286.00 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	254.00 FL	*- FL
4	1		*FRONT BONNET INSULATOR	Not Necessary	198.00 FL	*- FL
5	1		*SET FRONT BONNET INSULATOR CLIP	Not Necessary	80.00 FL	*- FL
6	1		*FRONT BUMPER	Deformed	1,987.00 FL	*1,781.00 FL
7	1		*FRONT BUMPER RETAINER LH+RH	N/S Not Necessary/O/S Deformed	224.00 FL	*58.00 FL
8	1		*FRONT BUMPER TOWING CAP	Deformed	89.00 FL	*40.00 FL
9	1		*FRONT BUMPER FOG LAMP RH	Cracked	197.00 FL	*197.00 FL
10	1		*FRONT BUMPER FOG LAMP GARNISH RH	Deformed	182.00 FL	*145.00 FL
11	1		*FRONT BUMPER NOZZLE RH	Cracked	165.00 FL	*165.00 FL
12	1		*FRONT BUMPER NOZZLE CAP RH	Deformed	78.00 FL	*48.00 FL
13	1		*FRONT BUMPER SPONGE	Cracked	145.00 FL	*145.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	847.00 FL	*715.00 FL
15	1		*FRONT BUMPER INNER GARNISH	Not Necessary	168.00 FL	*- FL
16	1		*SET FRONT BUMPER CLIP	Necessary	54.00 FS	*30.00 FS
17	1		*FRONT GRILLE ASSY	Cracked	1,606.00 FL	*1,208.00 FL
18	1		*FRONT GRILLE TOP GARNISH	Deformed	252.00 FL	*252.00 FL
19	1		*SET FRONT GRILLE TOP GARNISH CLIP	Not Necessary	50.00 FL	*- FL
20	2		*HEADLAMP LH+RH	Cracked	7,088.00 FL	*5,700.00 FL
21	1		*HEADLAMP BRACKET LH+RH	N/S Not Necessary /O/S Cracked	228.00 FL	*105.00 FL
22	1		*FRONT FENDER LH+RH	N/S Repair / O/S Bent	1,908.00 FL	*915.00 FL
23	1		*FRONT FENDER COWLING RH	Deformed	256.00 FL	*256.00 FL
24	1		*FRONT FENDER COWLING CLIP RH	Necessary	45.00 FS	*30.00 FS
25	1		*FRONT FENDER INNER PANEL RH	Repair	231.00 FL	*- FL
26	1		*FRONT SUPPORT PANEL	Repair	1,455.00 FL	*- FL
27	1		*FRONT SUPPORT PANEL SIDE GARNISH LH+RH	N/S Not Necessary / O/S Torn	96.00 FL	*48.00 FL
28	1		*AIRCON CONDENSOR	Not Necessary	1,330.00 FL	*- FL
29	1		*RADIATOR	Not Necessary	1,562.00 FL	*- FL
30	1		*COOLER	Not Necessary	860.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,811.00	14,199.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,471.20	1,413.90
Total Parts (\$\$)	22,339.80	12,785.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	700.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	850.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	60.00	30.00
4	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	100.00	40.00
5	TO R&R AIRCON CONDENSOR AND REFILL GAS	New	180.00	0.00
			Gross Labour Cost (S\$)	2,540.00
				1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >