

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKJ6659C
Nineteen

at Workshop m/s

of

Insured:

S6U12R

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

£ 17500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

751e

Vehicle: IN / OUT

Date:

Person Contacted:

21A613324

Veh No:

SKJ 6659C

Yr Regn:

26/94/13Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA

Make:

Volkswagen Golf A71-96 139F

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

119514

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZAUZDW096097Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40Zr18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

16/09/22

D.O.I.

20/09/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/7/2014 Rep/4/12. NAPP 417030/09/22 4/5 & 3000 internet Leray

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) ___S + RS, ___SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

)

TOTAL

NINETEEN AUTOWERKS PTE LTD

Blk 436 Tampines Street 43

#07-97 Singapore 520436

Tel: (65) 9674 1991

✉ nineteenautowerks@gmail.com

Not Authorized
 2/5 \$3000
 4 days
 20/9/22

**NINETEEN**
AUTOWERKS**ESTIMATE**

DATE:

16-Sep-22

DOA:

16-Sep-22

VEHICLE NO:

SKJ 6659 C

MAKE & MODEL:

Volkswagen Golf

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
LIST ITEMS			
Tailgate	1	\$2,088.90	2 \$2,088.90 X
Tailgate logo	1	\$80.00	11 \$80.00 x
Tailgate weatherstrip	1	\$225.00	11 \$225.00 x
Rear bumper	1	\$1,436.90	11 \$1,436.90 /
Rear bumper side retainer	2	\$120.60	11 \$241.20 X
Rear bumper centre retainer	1	\$164.30	11 \$164.30 X
Rear bumper reflector	2	\$89.00	11 \$178.00 X
Rear bumper reinforcement	1	\$552.30	2 \$552.30 X
Rear bumper diffuser	1	\$800.00	11 \$800.00 /
Rear number plate lamp	1	\$133.00	11 \$133.00 q
Rear end panel	1	\$811.00	2 \$811.00 q
Rear end panel top garnish	1	\$225.50	11 \$225.50 X
Exhaust pipe	1	\$2,800.00	2 \$2,800.00 X
Exhaust pipe mounting	2	\$87.50	11 \$175.00 X
		Total	\$9,911.10
		Less 10%	\$991.11
			\$8,919.99

SPECIAL NETT ITEMS

Rear license plate	1	\$60.00	50 \$60.00 40
Rear bumper clips (set)	1	\$80.00	11 \$80.00 50
Rear end panel top garnish clips (set)	1	\$50.00	11 \$50.00 X
Rear end panel sealant	1	\$100.00	11 \$100.00 X
Reverse sensor	1 set	\$350.00	shut \$350.00 200
			\$640.00
Parts Total			\$9,559.99

LABOUR CHARGES

Panel beating	\$1,500.00	580
Spray painting	\$1,200.00	800
Remove & refit exhaust pipe assy	11 \$200.00	X
Remove & refit reverse sensor and test	\$100.00	50
Check wiring system after disconnect & connect	\$100.00	30
To apply undercoating for rust roofing	11 \$100.00	X
Labour Total	\$3,200.00	

Total Parts and Labour Cost of Repair

LKK Auto Consultants hence notify

the Repairer of the following:

\$12,759.99

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3763.21
 20
 3010