

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009241/UNY3Q2**Date:** 06/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00011292200

**Claimant Vehicle  
No :** GBH3087P**Insured Vehicle  
No :** SLV1716D

Date of Loss: 13/09/2022

Nature of Claim: TP

Claim  
No: SNM22D206537/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBH3087P**

Make &amp; Model: TOYOTA DYNA 1.5T, 3.0 (M)

Engine No: 1KD2797479

Reg. Date: 18/04/2018 (Man. Year: 2018)

Chassis No: JTFAT35Y30K210356

Colour: Silver

Odometer: 118260 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Falken 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Falken 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,059.82	5,532.67	7,527.15	57.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	2,730.00	1,730.00	38.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,519.82</b>	<b>8,262.67</b>	<b>9,257.15</b>	<b>52.84</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>17,519.82</b>	<b>6,600.00</b>	<b>10,919.82</b>	<b>62.33</b>

**INSPECTION**

Date of Assignment: 20/09/2022

Date Inspected: 21/09/2022

Inspected At:

Jementah Motor Works (HQ)  
14 Defu Lane 10, #01-406  
Singapore 539195

Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 Oct 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH3087P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WIPER PANEL	Dented / Warped	262.50 FL	*262.50 FL
2	1		*WIPER MOTOR LINKAGE	Not Necessary	198.00 FL	*- FL
3	2		*FRONT HEADLAMPS	Cracked	2,161.00 FL	*2,161.00 FL
4	2		*FRONT SIDE LAMPS	No such part	305.80 FL	*- FL
5	1		*FRONT PANEL	Badly Dented	1,066.50 FL	*1,066.50 FL
6	1		*FRONT PANEL DYNA EMBLEM	Necessary	58.50 FL	*58.50 FL
7	2		*FRONT CORNER PANELS	Repair	553.00 FL	*- FL
8	1		*FRONT GRILLE ASSY	Cracked	648.69 FL	*648.69 FL
9	1		*SET FRONT GRILLE CLIP	Necessary	68.50 FL	*68.50 FL
10	1		*FRONT GRILLE LOGO	Necessary	75.00 FL	*75.00 FL
11	1		*FRONT BUMPER	Distorted	682.80 FL	*682.80 FL
12	2		*FRONT BUMPER BRACKETS	Bent	316.00 FL	*316.00 FL
13	1		*AIR CON BLOWER UNIT	Cracked	917.40 FL	*917.40 FL
14	1		*AIR CON COOLING COIL	Not Necessary	629.00 FL	*- FL
15	2		*REAR CHASSIS MEMBERS	Repair	1,970.40 FL	*- FL
16	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*20.00 FS
17	1		*REAR BUMPER ASSY	Bent	1,200.00 FS	*600.00 FS
18	1		*REAR NUMBER PLATE	Bent	50.00 FS	*20.00 FS
19	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
20	1		*SET REAR STOPPER RUBBER	Serviceable	480.00 FS	*- FS
21	1		*REAR FREEZER DOOR STAINLESS STEEL FRAME	Not Necessary	3,500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,538.09</b>	<b>7,096.89</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,478.27	1,564.22
<b>Total Parts (\$\$)</b>	<b>13,059.82</b>	<b>5,532.67</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING}	New	80.00	30.00
2	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO REMOVE ,REPLACE AIR CON CONDENSER ,REFILL GAS& CONDUCT LEAKAGE TEST	New	180.00	100.00
5	TO APPLY UNDERCOATING	New	200.00	50.00
6	PANEL BEATING	New	2,000.00	1,500.00
7	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,000.00
<b>Gross Labour Cost (S\$)</b>			<b>4,460.00</b>	<b>2,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >