

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009243/APA3Q2**Date:** 13/03/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000540

Claimant Vehicle No : SJX2888Y**Insured Vehicle No :** SKV5351H

Date of Loss: 13/09/2022

Nature of Claim: TP

Claim No: GOLAISCL2022-00011

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJX2888Y**

Make & Model: BMW 118i, 1.5 MSPT LED HL LED FL (A)

Engine No: 40065803B38A15A

Reg. Date: 30/10/2019 (Man. Year: 2019)

Chassis No: WBA7K320707E83730

Colour: White

Odometer: 42914 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,646.94	2,131.25	1,515.69	41.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	590.00	360.00	37.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,596.94	2,721.25	1,875.69	40.80
+ GST 7.00/7.00% (S\$)	321.79	190.49	131.30	40.80
Nett Amount (S\$)	4,918.73	2,911.74	2,006.99	40.80
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,063.74		

INSPECTION

Date of Assignment: 20/09/2022

Date Inspected: 04/10/2022 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2023)
Parts:	143	BMW 118I 1.5 MSPT LED HL LED FL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX2888Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,484.10 FL	*1,484.10 FL
2	2		*REAR BUMPER SIDE HOLDER -LH & RH	Not Necessary	136.20 FL	*- FL
3	1		*REAR BUMPER OUTER CHROME MOULDING	Deformed	218.40 FL	*218.40 FL
4	1		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	192.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	845.10 FL	*- FL
6	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,020.00 FL	*510.00 FL
7	4		*REVERSE SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$\$)	4,046.60 2,362.50
					- List Item Discount on L Items 10.00/10.00% (\$\$)	399.66 231.25
					Total Parts (\$\$)	3,646.94 2,131.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW PARTS	New	400.00	250.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	400.00	250.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
Gross Labour Cost (\$\$)			950.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >