

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009244/UVY3Q2**Date:** 05/10/2022**REFERENCE**

|                              |                                               |                             |                    |                                   |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMPCSNW00167642201 |                                   |
| <b>Claimant Vehicle No :</b> | SLP1049C                                      | <b>Insured Vehicle No :</b> | SMZ7173Y           |                                   |
| Date of Loss:                | 16/09/2022                                    | Nature of Claim:            | TP                 | Claim No: SNM22D206642/C02/TANCHC |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                                |             |                   |
|-----------------------------|------------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLP1049C</b>                                |             |                   |
| Make & Model:               | MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) | Engine No:  | 4A92CL8976        |
| Reg. Date:                  | 26/05/2017 (Man. Year: 2016)                   | Chassis No: | JMYSRCY1AGU006166 |
| Colour:                     | Blue                                           | Odometer:   | 128350 km         |
| Engine Capacity:            | 1590 cc                                        |             |                   |
| Market Value/New Car Price: | N/A                                            |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>              |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/60 R16    | Rear Tyre Size:  | 205/60 R16    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 23,798.69         | 6,915.35          | 16,883.34         | 70.94         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 5,610.00          | 3,220.00          | 2,390.00          | 42.60         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>29,408.69</b>  | <b>10,135.35</b>  | <b>19,273.34</b>  | <b>65.54</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>8,100.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>29,408.69</b>  | <b>8,100.00</b>   | <b>21,308.69</b>  | <b>72.46</b>  |

**INSPECTION**

|                             |            |                                                                                                              |
|-----------------------------|------------|--------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 20/09/2022 |                                                                                                              |
| Date Inspected:             | 20/09/2022 | Inspected At: SPEEDWERKZ PTE LTD (HQ)<br>13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre<br>Singapore 147807 |
| Estimated Period of Repair: | 9.0 days   |                                                                                                              |

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                                 |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                                 |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 03 Oct 2022)                                   |
| Parts:        | 143                                                                                                                                                                          | MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                               |
| Print Code:   | (Unsubmitted, no print-code for SLP1049C)                                                                                                                                    |                                                                                 |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                                 |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                                 |

Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOT                           | Repair        | 923.00 FL   | *- FL        |
| 2   | 1   |          | *REAR BOOT LID BOARD                 | Not Necessary | 247.60 FL   | *- FL        |
| 3   | 1   |          | *REAR THIRD BRAKE LIGHT              | Not Necessary | 385.50 FL   | *- FL        |
| 4   | 2   |          | *REAR BOOT LID REFLECTOR             | Not Necessary | 790.00 FL   | *- FL        |
| 5   | 1   |          | *REAR BOOT RUBBER                    | Twisted       | 123.00 FL   | *123.00 FL   |
| 6   | 1   |          | *REAR BOOT LOCK                      | Not Necessary | 135.00 FL   | *- FL        |
| 7   | 1   |          | *REAR BOOT LOCK CATCH                | Not Necessary | 59.00 FL    | *- FL        |
| 8   | 2   |          | *REAR BOOT HINGE                     | Not Necessary | 224.00 FL   | *- FL        |
| 9   | 1   |          | *REAR CENTRE GARNISH                 | Not fitted    | 258.00 FL   | *- FL        |
| 10  | 1   |          | *REAR BOOT EMBLEM (MIVEC)            | Not fitted    | 85.00 FL    | *- FL        |
| 11  | 1   |          | *REAR BOOT EMBLEM (LANCER)           | Not fitted    | 85.00 FL    | *- FL        |
| 12  | 1   |          | *REAR BOOT CENTRE LOGO               | Necessary     | 82.00 FL    | *60.00 FL    |
| 13  | 1   |          | *REAR END PANEL                      | Dented / Bent | 590.00 FL   | *564.00 FL   |
| 14  | 1   |          | *REAR END PANEL TOP GARNISH          | Not Necessary | 236.00 FL   | *- FL        |
| 15  | 1   |          | *REAR TAIL LAMP (LED)                | N/S Cracked   | 1,298.00 FL | *550.00 FL   |
| 16  | 2   |          | *REAR TAIL LAMP PANEL                | Repair        | 204.00 FL   | *- FL        |
| 17  | 2   |          | *REAR FENDER                         | Not Necessary | 1,576.00 FL | *- FL        |
| 18  | 1   |          | *REAR FENDER INNER GARNISH           | N/S Torn      | 418.00 FL   | *209.00 FL   |
| 19  | 2   |          | *REAR FENDER DUST COVER              | Not Necessary | 80.00 FL    | *- FL        |
| 20  | 1   |          | *REAR FENDER INNER WHEEL HOUSE PANEL | Not Necessary | 1,475.00 FL | *- FL        |
| 21  | 1   |          | *REAR BUMPER                         | Distorted     | 848.00 FL   | *848.00 FL   |
| 22  | 2   |          | *REAR BUMPER SIDE RETAINER           | Bent          | 120.00 FL   | *50.00 FL    |
| 23  | 1   |          | *REAR BUMPER REINFORCEMENT           | Bent          | 429.00 FL   | *231.00 FL   |
| 24  | 1   |          | *REAR BUMPER REFLECTOR               | N/S Cracked   | 76.00 FL    | *38.00 FL    |
| 25  | 1   |          | *REAR SPARE TYRE PANEL               | Repair        | 1,012.00 FL | *- FL        |
| 26  | 1   |          | *REAR SPARE TYRE TOP COVER BOARD     | Not Necessary | 350.00 FL   | *- FL        |
| 27  | 1   |          | *REAR SPARE TYRE SCREW               | Not Necessary | 68.00 FL    | *- FL        |
| 28  | 1   |          | *REAR EXHAUST SILENCER               | Not Necessary | 952.00 FL   | *- FL        |
| 29  | 2   |          | *REAR EXHAUST RUBBER                 | Not Necessary | 82.00 FL    | *- FL        |
| 30  | 1   |          | *REAR EXHAUST CHROME PIPE            | Not Necessary | 125.00 FL   | *- FL        |
| 31  | 2   |          | *REAR NUMBER PLATE LAMP              | Not Necessary | 120.00 FL   | *- FL        |
| 32  | 1   |          | *FRONT BONNET                        | Repair        | 1,252.00 FL | *- FL        |
| 33  | 1   |          | *FRONT BONNET INSULATOR              | Not Necessary | 351.00 FL   | *- FL        |
| 34  | 1   |          | *FRONT BONNET LOCK                   | Not Necessary | 265.50 FL   | *- FL        |
| 35  | 2   |          | *FRONT BONNET HINGE                  | Not Necessary | 152.00 FL   | *- FL        |
| 36  | 1   |          | *FRONT SUPPORT PANEL                 | Bent          | 956.50 FL   | *548.00 FL   |
| 37  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH     | Not Necessary | 312.20 FL   | *- FL        |
| 38  | 1   |          | *FRONT HEAD LAMP N/S                 | Cracked       | 985.00 FL   | *985.00 FL   |
| 39  | 1   |          | *FRONT FENDER                        | Repair        | 785.00 FL   | *- FL        |
| 40  | 2   |          | *FRONT FENDER COWLING                | Not Necessary | 390.00 FL   | *- FL        |
| 41  | 2   |          | *FRONT FENDER INNER PANEL            | Not Necessary | 1,710.00 FL | *- FL        |
| 42  | 1   |          | *FRONT FOG LAMP SIDE LED DAY LIGHT   | N/S Cracked   | 480.00 FL   | *240.00 FL   |
| 43  | 1   |          | *FRONT BUMPER                        | Distorted     | 1,231.00 FL | *1,031.00 FL |
| 44  | 1   |          | *FRONT BUMPER FOG LAMP COVER         | N/S Twisted   | 230.00 FL   | *115.00 FL   |
| 45  | 1   |          | *FRONT FOG LAMP N/S                  | Cracked       | 248.00 FL   | *248.00 FL   |
| 46  | 1   |          | *FRONT HEAD LAMP PANEL               | Repair        | 135.00 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------|---------------|------------|------------|
| 47  | 1   |          | *FRONT GRILLE ASSY                | Cut           | 395.50 FL  | *300.00 FL |
| 48  | 1   |          | *FRONT BUMPER LOWER GRILLE RIM    | Not fitted    | 267.50 FL  | *- FL      |
| 49  | 1   |          | *FRONT BUMPER LOWER GRILLE        | Cut           | 214.50 FL  | *214.50 FL |
| 50  | 1   |          | *FRONT BUMPER REINFORCEMENT       | Bent          | 589.50 FL  | *451.00 FL |
| 51  | 2   |          | *FRONT BUMPER SIDE RETAINER       | Bent          | 56.00 FL   | *56.00 FL  |
| 52  | 1   |          | *FRONT BUMPER TOP BEAM            | No such part  | 314.80 FL  | *- FL      |
| 53  | 1   |          | *FRONT BUMPER PLATE GARNISH       | Not Necessary | 89.00 FL   | *- FL      |
| 54  | 1   |          | *AIR HOSE                         | Not Necessary | 128.00 FL  | *- FL      |
| 55  | 1   |          | *AIR CLEANER HOSE                 | Not Necessary | 55.00 FL   | *- FL      |
| 56  | 1   |          | *FRONT NUMBER PLATE               | Not Necessary | 45.00 FS   | *- FS      |
| 57  | 3   |          | *REAR END PANEL TOP GARNISH CLIPS | Not Necessary | 19.50 FS   | *- FS      |
| 58  | 1   |          | *REAR SPARE TYRE PANEL INSULATOR  | Not Necessary | 250.00 FS  | *- FS      |
| 59  | 1   |          | *NUMBER PLATE (REAR)              | Bent          | 90.00 FS   | *40.00 FS  |
| 60  | 1   |          | *SET REAR BUMPER SENSOR           | Shorted       | 350.00 FS  | *200.00 FS |
| 61  | 1   |          | *SET FRONT BUMPER LOWER LIP       | Cracked       | 500.00 FS  | *500.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>26,303.60</b> | <b>7,601.50</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 2,504.91         | 686.15          |
| <b>Total Parts (\$\$)</b>                                  | <b>23,798.69</b> | <b>6,915.35</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                  |          |                 |                 |
| 1                               | TO CHECK WIRING                                  | New      | 200.00          | 30.00           |
| 2                               | TUFF KOTE                                        | New      | 350.00          | 60.00           |
| 3                               | REMOVE AND REFIX UPHOLSTERY                      | New      | 250.00          | 80.00           |
| 4                               | REMOVE AND REFIX EXHAUST PIPE                    | New      | 160.00          | 0.00            |
| 5                               | REMOVE & REFIX REVERSE SENSOR                    | New      | 150.00          | 50.00           |
| 6                               | REMOVE AND REPLACE SPARE PARTS AND PANEL BEATING | New      | 2,500.00        | 1,400.00        |
| 7                               | RESPRAY PAINTING                                 | New      | 2,000.00        | 1,600.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                  |          | <b>5,610.00</b> | <b>3,220.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >