



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 9090M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (N)	CUT / TORN	1,580.00	1,580.00
1	FRONT BUMPER SIDE RETAINER N/S	NOT NECESSARY	55.00	-
2	FRONT BUMPER PARKING SENSOR @\$269.80	NOT NECESSARY	539.60	-
1	FRONT LICENCE PLATE GARNISH (N)	TORN	158.90	112.00
1	FRONT CENTRE GRILLE (N) (PITTED)	NOT CONSISTENT WITH THE IMPACT	1,100.00	-
	LESS 10% DISCOUNT		-343.35	-169.20
			3,090.15	1,522.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENCE PLATE (SN)	BENT	80.00	40.00
			80.00	40.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.}		80.00	50.00
	TO REINSTALL OF FRONT BUMPER PARKING SENSOR . }		80.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.		400.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		400.00	200.00
			960.00	450.00
	GRAND TOTAL		4,130.15	2,012.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/AGI22009247/Uvy3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.