



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 5593B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DENTED	538.20	538.20
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	BENT	18.40	18.40
16	FRONT BUMPER CLIPS @\$3.50 (CONSISTENT)	NECESSARY	56.00	56.00
1	FRONT BUMPER DAY LIGHT LH (CONSISTENT)	CRACKED	184.70	184.70
1	HEAD LAMP LH (CONSISTENT)	CRACKED	1,216.40	1,216.40
1	HEAD LAMP COVER BRACKET (CONSISTENT)	CRACKED	31.90	31.90
1	FRONT GRILLE (CONSISTENT)	CRACKED	314.90	314.90
8	FRONT GRILLE CLIPS @\$3.50 (CONSISTENT)	NOT NECESSARY	28.00	-
1	FRONT GRILLE BADGE (CONSISTENT)	NOT NECESSARY	67.40	-
1	FRONT GRILLE EMBLEM "RS" (CONSISTENT)	NOT NECESSARY	62.10	-
1	FOG LAMP LH (CONSISTENT)	CRACKED	284.30	284.30
1	FOG LAMP COVER (CONSISTENT)	TWISTED	38.20	38.20
	LESS 20% DISCOUNT		-568.10	-536.60
			2,272.40	2,146.40
	<u>LABOUR</u>			
	CHECK WIRING SYSTEM.		50.00	20.00
	TO RESPRAY AFFECTED AREAS.		550.00	350.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR & ALIGNED ALL PARTS.		550.00	300.00
			1,150.00	670.00
	GRAND TOTAL		3,422.40	2,816.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,200.00

Report Ref No. CS/ASM22009248/Uwy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.