

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 8484J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER-RR BUMPER (SN)	DENTED	684.00	684.00
1	COVER-RR BUMPER, UPR (SN)	CUT	294.00	294.00
1	BEAM-RR BUMPER (SN)	BROKEN	438.00	438.00
1	BRACKET-RR RAIL UPR MTG, LH (SN)	NOT NECESSARY	4.00	-
1	BRACKET-RR RAIL UPR MTG, RH (SN)	NOT NECESSARY	4.00	-
2	BRACKET-RR BEAM LWR MTG @\$6.00 (SN)	NOT NECESSARY	12.00	-
1	BRACKET-RR BEAM LWR, CTR (SN)	NOT NECESSARY	6.00	-
1	ANTENNA ASSY-SMARTKEY (SN)	NOT NECESSARY	69.00	-
1	BRACKET-RR RAIL UPR MTG, LH (SN)	NOT NECESSARY	4.00	-
1	BRACKET-RR RAIL UPR MTG, RH (SN)	NOT NECESSARY	4.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			1,569.00	1,436.00
	<u>LABOUR</u>			
	REPLACE REAR BUMPER PANEL & AFFECTED AREA REPAIR ON END PANEL.		1,920.00	640.00
	PAINT WORK ON REAR BUMPER PANEL & END PANEL.		1,650.00	550.00
	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR.		150.00	80.00
	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR.	NOT NECESSARY	180.00	-
	TO APPLY SEALANT ON AFFECTED AREA.	NOT NECESSARY	120.00	-
	PERFORM RUST PREVENTION.		120.00	40.00
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.		150.00	120.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		280.00	280.00
			4,570.00	1,710.00
	GRAND TOTAL		6,139.00	3,146.00



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS	3,146.0)
RECOMMENDED COST OF REPAIRS	3,140	.UU

Report Ref No. CS/AWA22009251/Ewy3m4



Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser