



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 5257M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED / DENTED	466.30	466.30
1	LEFT TAILLAMP	SCRATCHED	331.10	331.10
1	LEFT TAILLAMP CORNER PANEL	TO REPAIR SEE LABOUR	101.80	-
1	REAR BUMPER LEFT RETAINER	DISTORTED	35.80	35.80
1	CORNER PANEL RETAINER	SERVICEABLE	43.80	-
	LESS 25% DISCOUNT		-244.70	-208.30
			734.10	624.90
	<u>LABOUR</u>			
	PANEL KNOCKING. INCLUSIVE OF THE REPAIR OF LEFT TAILLAMP CORNER PANEL.		350.00	200.00
	SPRAY PAINTING.		450.00	150.00
	WIRE CHECKING.		80.00	20.00
			880.00	370.00
	GRAND TOTAL		1,614.10	994.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			800.00

Report Ref No. CS/SMR22009254/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.