

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOMO		Ref:	CS/SMR22009254/Kqy3e2	
	60 WOODLANDS I E4SINGAPORE 75		Date:	04/10/2022	
				Code:	SMR
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1038E	Veh. Inspected		PC 5257M
	Policy No.		Coverage (\$)		0.00
	Claim No.	TAX/09/22/2024	Excess (\$)		0.00
	Assign From	HUA YEN	Assign Date		20/09/2022
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE (A)	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	KDH2230029535	Colour		WHITE
	Odometer	409979 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/55Z R17	ALVENTI		7 mm
	L/H Front Tyre	225/55Z R17	ALVENTI		7 mm
	R/H Rear Tyre	225/55Z R17	ALVENTI		7 mm
	L/H Rear Tyre	225/55Z R17	ALVENTI		7 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/09/2022	Inspection Dat	е	26/09/2022
	Survey held at HWA SENG SPRAY PAINTING PTE LTD				
		160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				