

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22009256/EYA3Q2**Date:** 19/04/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000387471-01
<b>Claimant Vehicle No :</b>	SLT7379P	<b>Insured Vehicle No :</b>	SLQ9673S
Date of Loss:	14/09/2022	Nature of Claim:	TP
		Claim No:	202222006774

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT7379P</b>		
Make & Model:	MAZDA 3, 1.5 SEDAN AT LED EU6 (A)	Engine No:	P520450333
Reg. Date:	09/11/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0157583
Colour:	Grey	Odometer:	150577 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Rydanz 4 mm	Rear Left Side:	Rydanz 4 mm
Front Right Side:	Rydanz 4 mm	Rear Right Side:	Rydanz 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,888.00	2,182.00	706.00	24.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	930.00	1,170.00	55.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,988.00</b>	<b>3,112.00</b>	<b>1,876.00</b>	<b>37.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>(S\$)</b>	4,988.00	2,500.00	2,488.00	49.88
<b>+ GST 8.00/8.00% (S\$)</b>	399.04	200.00	199.04	49.88
<b>Nett Amount (S\$)</b>	<b>5,387.04</b>	<b>2,700.00</b>	<b>2,687.04</b>	<b>49.88</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,942.00</b>		

INSPECTION

Date of Assignment:	20/09/2022		
Date Inspected:	20/09/2022	Inspected At:	Lion City Rentals Pte Ltd (HQ) No 4 Jln Besut Singapore 619557
Estimated Period of Repair:	4.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts:	143	MAZDA 3 1.5 SEDAN AT LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT7379P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	980.00 FL	*980.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	550.00 FL	*- FL
3	1		*FRONT RH FENDER	Dented	580.00 FL	*580.00 FL
4	1		*FRONT RH FENDER LINER	Crushed	180.00 FL	*180.00 FL
5	1		*FRONT RH HEADLAMP	Broken	950.00 FL	*950.00 FL
6	1		*WIPER MOTOR	Not Necessary	120.00 FL	*- FL
7	1		*WIPER MOTOR TANK	Not Necessary	150.00 FL	*- FL
8	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
					Sub Total (\$\$)	3,590.00 2,720.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	702.00 538.00
					Total Parts (\$\$)	2,888.00 2,182.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER ,RH FENDER ,FRONT HEADLAMP ,WATER TANK OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGE PARTS	New	1,000.00	400.00
2	TO RESPRAY FRONT BUMPER ,FRONT RH FENDER	New	800.00	500.00
3	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	300.00	30.00
Gross Labour Cost (\$\$)			2,100.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >