

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS22009257/EQY3M4**Date:** 20/02/2023**REFERENCE**

Insured/Claimant:	ZHENG JIANFAN	Policy No:	SP2000325952	Claim No:	202222006658JK
Date of Loss:	09/09/2022	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM372D		Engine No:	H1623356B48B20A
Make & Model:	BMW 520I, 2.0 LED NAV MSPT (A)		Chassis No:	WBAJA12020BT82716
Reg. Date:	14/06/2019 (Man. Year: 2019)		Odometer:	100158 km
Colour:	Black			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	S\$171,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,244.30	9,607.10	8,637.20	47.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,927.00	5,753.00	8,174.00	58.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,171.30	15,360.10	16,811.20	52.26
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	31,571.30	14,760.10	16,811.20	53.25
+ GST 7.00/7.00% (\$\$)	2,209.99	1,033.21	1,176.78	53.25
Nett Amount (\$\$)	33,781.29	15,793.31	17,987.98	53.25

INSPECTION

Date of Assignment:	20/09/2022	Performance Motors Limited (Alexandra)
Date Inspected:	27/09/2022 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	5.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Note: According to the repairer they still pending for owner respond on this OD claiming.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,514.50 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	BMW 520i 2.0 LED NAV MSPT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM372D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C CLIP FOR PLASTIC NUT 30PIECES	Necessary	33.00 FS	*33.00 FS
2	1		*ALLOY RIM 8JX19 DOUBLE SPK 664M	Not Necessary	1,827.95 FS	*- FS
3	1		*LH ENGINE HOOD HINGE	* Check	101.95 FS	*- FS
4	1		*REAR LH SIDE PANEL	Not Necessary	2,024.10 FS	*- FS
5	1		*ALUMINIUM ENGINE HOOD	Dented	2,497.90 FS	*2,497.90 FS
6	1		*FRT BUMPER CARRIER	* Check	758.85 FS	*- FS
7	1		*LH GUIDE TOP	* Check	36.20 FS	*- FS
8	1		*FRT BUMPER TOP IMPACT ABSORBER (M)	* Check	76.15 FS	*- FS
9	1		*GRILLE AIR INLET MIDDLE	* Check	98.95 FS	*- FS
10	1		*LH GRILLE AIR INLET OPEN	* Check	84.80 FS	*- FS
11	1		*LH GRILLE COVER	* Check	77.75 FS	*- FS
12	1		*LH FOG LAMP SUPPORT (M)	* Check	67.15 FS	*- FS
13	1		*LH FOG LAMP SUPPORT (M)	* Check	67.15 FS	*- FS
14	1		*LH FINISHER	* Check	77.75 FS	*- FS
15	1		*FRT BUMPER TOWING COVER PRIMED	Not Necessary	53.70 FS	*- FS
16	1		*FRT BUMPER PANEL PRIMED (M)	Dented	1,745.00 FS	*1,745.00 FS
17	1		*SET MOUNTING PDC/PMA SENSOR FRT	Necessary	71.60 FS	*71.60 FS
18	1		*TRIM GRILLE FRT (I CAM)	Not Necessary	25.90 FS	*- FS
19	1		*FRT LH GRILLE (M/SPORT)	Cut	148.70 FS	*148.70 FS
20	1		*FRT RH GRILLE (M/SPORT)	Not Necessary	148.70 FS	*- FS
21	1		*LH TURN INDICATOR EXTERIOR MIRROR	Not Necessary	86.55 FS	*- FS
22	1		*LH COVER CAP PRIMED	Not Necessary	169.05 FS	*- FS
23	1		*LH HEATED OUTSIDE MIRROR MEMORY BUS	Not Necessary	1,080.40 FS	*- FS
24	1		*HOLDER BONNET ACTUATOR	Not Necessary	34.35 FS	*- FS
25	2		*GAS FILLED STRUT ENGINE COMPARTMENT	Not Necessary	267.00 FS	*- FS
26	1		*LOCK LH	Not Necessary	128.40 FS	*- FS
27	2		*LOCK TOP PART	Not Necessary	154.10 FS	*- FS
28	1		*LEVER F ENGINE HOOD MECHANISM (SCHW	Not Necessary	40.75 FS	*- FS
29	1		*CLIP (SCHWARZ)	Not Necessary	6.70 FS	*- FS
30	20		*EXPANDING RIVET D=8MM	Not Necessary	22.00 FS	*- FS
31	1		*CONNECTION FRT TOP	Not Necessary	216.30 FS	*- FS
32	1		*FRT PANEL SUPPORT	* Check	67.80 FS	*- FS
33	1		*RH HEADLIGHT MOUNTING	Not Necessary	211.95 FS	*- FS
34	1		*COVERING CROSS MEMBER (ECE)	Not Necessary	29.70 FS	*- FS
35	1		*AIR DUCT RADIATOR TOP	Not Necessary	79.30 FS	*- FS
36	1		*LH AIR DUCT BRAKE WHEEL ARCH	Not Necessary	52.85 FS	*- FS
37	1		*AIR FLAPS TOP	Not Necessary	291.55 FS	*- FS
38	1		*AIR FLAP CONTROL ACTIVE TOP	Not Necessary	99.15 FS	*- FS
39	1		*FRT ENGINE BONNET SEAL	Not Necessary	34.55 FS	*- FS
40	1		*BONNET LH SIDE GASKET	Not Necessary	34.55 FS	*- FS
41	1		*LH HEADLIGHT LED AHL HIGH (ICON LIG	Broken	4,960.90 FS	*4,960.90 FS
42	3		*EXPANDING NUT 7X7 MM	Not Necessary	3.15 FS	*- FS
43	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **18,244.30** **9,607.10**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BONNET, FRONT BUMPER, SUPPORT PANEL, REAR LEFT FENDER, SIDE MIRROR ASSY, MAKE GOOD FRONT LEFT FENDER AND REAR LEFT DOOR	New	6,375.00	2,125.00
2	TO RESPRAY BONNET, FRONT BUMPER, FRONT LEFT FENDER, SIDE MIRROR CAP LEFT, LEFT REAR DOOR, LEFT REAR FENDER, ROOF FRAME AND AFFECTED AREAS	New	5,891.00	2,220.00
3	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL).1X	New	118.00	112.00
4	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL).1X	New	531.00	504.00
5	TO REPLACE LEFT HEADLIGHT	New	481.00	456.00
6	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
7	TO CHECK ELECTRICAL	New	177.00	168.00
8	TO REPLACE WHEEL RIM INCLUDING BALANCING 1X	New	94.00	0.00
9	TO SUPPLY FRONT EMBOSS NUMBER PLATE	New	83.00	0.00
Gross Labour Cost (\$\$)			13,927.00	5,753.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >