

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**HL Assurance Pte Ltd  
11 Keppel Road, #11-01 ABI Plaza  
Singapore 089057**Our File No:** CS/HLA22009258/ENY3E2  
**Date:** 18/04/2023REFERENCE

|                   |                       |                  |              |
|-------------------|-----------------------|------------------|--------------|
| Insured/Claimant: | CHAN CHENG MIN SERENE | Policy No:       | MP319661     |
| Date of Loss:     | 19/09/2022            | Nature of Claim: | OD           |
|                   |                       | Claim No:        | MPC03690/ANA |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLA1311Z</b>                   | Engine No:  | 31606236B38A15A   |
| Make & Model:               | BMW 216I, 1.5 (A)                 | Chassis No: | WBA2X920907H27845 |
| Reg. Date:                  | 26/02/2021 (Man. Year: 2020)      | Odometer:   | 21928 km          |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1499 cc                           |             |                   |
| Market Value/New Car Price: | S\$143,000.00                     |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/55 R17    | Rear Tyre Size:  | 205/55 R17    |
| Front Left Side:  | Michelin 4 mm | Rear Left Side:  | Michelin 4 mm |
| Front Right Side: | Michelin 4 mm | Rear Right Side: | Michelin 4 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>               | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                               | 13,908.75         | 10,780.90         | 3,127.85          | 22.49         |
| Miscellaneous Items                 | 0.00              | 0.00              | 0.00              |               |
| Labour                              | 18,827.00         | 12,924.00         | 5,903.00          | 31.35         |
| Paintwork Labour                    | 0.00              | 0.00              | 0.00              |               |
| Towing                              | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b> | <b>32,735.75</b>  | <b>23,704.90</b>  | <b>9,030.85</b>   | <b>27.59</b>  |
| <b>- Excess (S\$)</b>               | 600.00            | 600.00            | 0.00              | 0.00          |
| <b>(S\$)</b>                        | 32,135.75         | 23,104.90         | 9,030.85          | 28.10         |
| <b>+ GST 8.00/8.00% (S\$)</b>       | 2,570.86          | 1,848.39          | 722.47            | 28.10         |
| <b>Nett Amount (S\$)</b>            | <b>34,706.61</b>  | <b>24,953.29</b>  | <b>9,753.32</b>   | <b>28.10</b>  |

INSPECTION

|                             |                          |                                                                                                                 |
|-----------------------------|--------------------------|-----------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 20/09/2022               |                                                                                                                 |
| Date Inspected:             | 21/09/2022 Inspected At: | Performance Motors Limited (Alexandra)<br>303 Alexandra Road, Sime Darby Performance Centre<br>Singapore 159941 |
| Estimated Period of Repair: | 10.0 days                |                                                                                                                 |

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 18 Apr 2023)      |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLA1311Z)                                                                                                                                    |                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                    |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *SUNDRIES                          | Necessary     | 150.00 FS   | *150.00 FS   |
| 2   | 1   |          | *RH WISHBONE WITH RUBBER MOUNTING  | Not Necessary | 290.45 FS   | *- FS        |
| 3   | 1   |          | *HUB CAP WITH CHROME EDGE          | Repair        | 31.30 FS    | *- FS        |
| 4   | 1   |          | *FRT RH FENDER                     | Dented        | 639.70 FS   | *639.70 FS   |
| 5   | 1   |          | *BONNET                            | Dented        | 1,521.90 FS | *1,521.90 FS |
| 6   | 1   |          | *BONNET LH HINGE                   | Not Necessary | 115.85 FS   | *- FS        |
| 7   | 1   |          | *BONNET RH HINGE                   | Not Necessary | 115.85 FS   | *- FS        |
| 8   | 1   |          | *RH UPPER FRONT DOOR HINGE         | Not Necessary | 62.95 FS    | *- FS        |
| 9   | 1   |          | *RH LOWER FRT DOOR HINGE           | Not Necessary | 62.95 FS    | *- FS        |
| 10  | 1   |          | *FRT RH DOOR                       | Dented        | 1,130.75 FS | *1,130.75 FS |
| 11  | 1   |          | *FRT CROSSLINK                     | Not Necessary | 114.85 FS   | *- FS        |
| 12  | 1   |          | *FRT LH BOTTOM DEFORMATION ELEMENT | Not Necessary | 91.60 FS    | *- FS        |
| 13  | 1   |          | *FRT RH BOTTOM DEFORMATION ELEMENT | Not Necessary | 91.60 FS    | *- FS        |
| 14  | 1   |          | *FRT BUMPER BOTTOM CARRIER         | Bent          | 156.00 FS   | *156.00 FS   |
| 15  | 1   |          | *FRT LH TOP DEFORMATION ELEMENT    | Broken        | 106.75 FS   | *106.75 FS   |
| 16  | 1   |          | *FRT RH TOP DEFORMATION ELEMENT    | Broken        | 106.75 FS   | *106.75 FS   |
| 17  | 1   |          | *LH FOG LAMP SUPPORT               | Not Necessary | 80.55 FS    | *- FS        |
| 18  | 1   |          | *RH FOG LAMP SUPPORT               | Missing       | 80.55 FS    | *80.55 FS    |
| 19  | 1   |          | *FRT BUMPER TOP CARRIER            | Dented        | 400.80 FS   | *400.80 FS   |
| 20  | 1   |          | *LH FINISHER                       | Not Necessary | 50.90 FS    | *- FS        |
| 21  | 1   |          | *RH FINISHER                       | Not Necessary | 50.90 FS    | *- FS        |
| 22  | 1   |          | *LH MOLDING (SPORT)                | Not Necessary | 62.55 FS    | *- FS        |
| 23  | 1   |          | *RH MOLDING (SPORT)                | Not Necessary | 62.55 FS    | *- FS        |
| 24  | 1   |          | *IMPACT ABSORBER TOP               | Crushed       | 59.60 FS    | *59.60 FS    |
| 25  | 1   |          | *FRT BUMPER FLAP TOWING EYE PRIMED | Not Necessary | 43.95 FS    | *- FS        |
| 26  | 1   |          | *FRT BUMPER PRIMED PANEL (PMA)     | Dented        | 950.80 FS   | *950.80 FS   |
| 27  | 1   |          | *LH GRID LATERAL (LINES/PDC)       | Not Necessary | 96.95 FS    | *- FS        |
| 28  | 1   |          | *RH GRID LATERAL (LINES/PDC)       | Not Necessary | 96.95 FS    | *- FS        |
| 29  | 1   |          | *GRILLE, FRONT LEFT                | Not Necessary | 114.90 FS   | *- FS        |
| 30  | 1   |          | *GRILLE, FRONT RIGHT               | Not Necessary | 114.90 FS   | *- FS        |
| 31  | 1   |          | *LH SUPPORT HEADLIGHT ARM          | Not Necessary | 134.25 FS   | *- FS        |
| 32  | 1   |          | *RH SUPPORT HEADLIGHT ARM          | Not Necessary | 134.25 FS   | *- FS        |
| 33  | 1   |          | *FRONT CROSSLINK                   | Not Necessary | 129.50 FS   | *- FS        |
| 34  | 1   |          | *FRONT PANEL V STRUT               | Bent          | 126.80 FS   | *126.80 FS   |
| 35  | 1   |          | *AIR DUCT                          | Broken        | 276.05 FS   | *276.05 FS   |
| 36  | 1   |          | *RH HEADLIGHT LED TECHNOLOGY       | Cut           | 2,399.10 FS | *2,399.10 FS |
| 37  | 1   |          | *AIR INTAKE DUCT                   | Broken        | 180.50 FS   | *180.50 FS   |
| 38  | 1   |          | *CHARGE AIR COOLER                 | Bent          | 592.55 FS   | *592.55 FS   |
| 39  | 1   |          | *FRT BUMPER RH INSERT              | Broken        | 14.20 FS    | *14.20 FS    |
| 40  | 1   |          | *FRT RH SIDE PANEL TOP MOUNTING    | Broken        | 19.00 FS    | *19.00 FS    |
| 41  | 1   |          | *GRATE CENTRE CLOSED (LINES/PDC)   | Broken        | 161.55 FS   | *161.55 FS   |
| 42  | 1   |          | *TRIM STRIP CENTRE (SPORT)         | Broken        | 55.05 FS    | *55.05 FS    |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                          | Condition | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|-----------|-------------|--------------|
| 43  | 1   |          | *COVERING CENTER                     | Broken    | 45.50 FS    | *45.50 FS    |
| 44  | 1   |          | *FRT RH GRILLE (SPORT)               | Broken    | 113.15 FS   | *113.15 FS   |
| 45  | 3   |          | *EXPANDING RIVET                     | Necessary | 1.35 FS     | *1.35 FS     |
| 46  | 1   |          | *RH SEALING COLUMN B BOTTOM          | Broken    | 57.90 FS    | *57.90 FS    |
| 47  | 1   |          | *PLAQUE 82MM                         | Necessary | 72.85 FS    | *72.85 FS    |
| 48  | 1   |          | *RH SILL TRIM PRIMED                 | Broken    | 301.55 FS   | *301.55 FS   |
| 49  | 1   |          | *CONDENSER AIR CONDITIONING WITH DRI | Bent      | 1,032.05 FS | *1,032.05 FS |
| 50  | 3   |          | *EXPANDING NUT 7X7 MM                | Necessary | 3.15 FS     | *3.15 FS     |
| 51  | 1   |          | *LABEL COOLANT 520+/-15G             | Necessary | 25.00 FS    | *25.00 FS    |
| 52  | 1   |          | *ALLOY RIM 7.5X17 DOUBLE SPK 549     | Repair    | 977.35 FS   | *- FS        |

F=Franchise part. S=SpcNett.

|                         |                  |                  |
|-------------------------|------------------|------------------|
| <b>Total Parts (\$)</b> | <b>13,908.75</b> | <b>10,780.90</b> |
|-------------------------|------------------|------------------|

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                          | Lab.Type | Repairer's       | Amount           |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|------------------|
| <b>Labour Items</b>            |                                                                                                                                      |          |                  |                  |
| 1                              | TO REPLACE BUMPER FRONT PANEL, BONNET, FRONT RIGHT SIDE PANEL, FRONT RIGHT DOOR AND FRONT ATTACHMENTS. TO REPAIR REAR RIGHT DOOR     | New      | 6,800.00         | 4,675.00         |
| 2                              | TO SPRAY PAINT BUMPER FRONT PANEL, FRONT RIGHT SIDE PANEL, BONNET, BOTH RIGHT DOORS, A PILLAR RIGHT                                  | New      | 5,664.00         | 4,741.00         |
| 3                              | TO REPLACE RIGHT HEADLIGHT                                                                                                           | New      | 481.00           | 456.00           |
| 4                              | TO SUPPLY FRONT EMBOSS NUMBER PLATE                                                                                                  | New      | 83.00            | 83.00            |
| 5                              | TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR) | New      | 531.00           | 504.00           |
| 6                              | TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (1X)                                    | New      | 531.00           | 504.00           |
| 7                              | TO REPLACE WHEEL RIM INCLUDING BALANCING (1X). FRONT RIGHT                                                                           | New      | 94.00            | 0.00             |
| 8                              | TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND REPLACE DAMAGED PARTS                                                      | New      | 2,655.00         | 0.00             |
| 9                              | TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS                        | New      | 177.00           | 168.00           |
| 10                             | TO REPLACE CHARGE AIR COOLER INCLUDE CONDUCTING CHECKS FOR LEAK AND PROPER FUNCTION                                                  | New      | 504.00           | 504.00           |
| 11                             | TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)                                                                                   | New      | 354.00           | 336.00           |
| 12                             | TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK                        | New      | 953.00           | 953.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                      |          | <b>18,827.00</b> | <b>12,924.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >