



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22009259/Avy3e2

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 04/11/2022

ATTN: CHARLOTTE CHEW

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 1771S	Veh. Inspected	SGD 5668L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1188742-002	Excess (\$)	0.00
Assign From	DIANA TAY	Assign Date	20/09/2022

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NRE1610003112	Colour	WHITE
Odometer	154767 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	WINDFORCE	6 mm
L/H Front Tyre	185/70 R14	WINDFORCE	6 mm
R/H Rear Tyre	185/70 R14	WINDFORCE	6 mm
L/H Rear Tyre	185/70 R14	WINDFORCE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	14/09/2022	Inspect Date / Time	20/09/2022 ( 02:50 PM )
Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**