



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 8192K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR LH	DENTED	1,899.00	1,899.00
1	FRONT DOOR OUTER STRIP LH	NOT NECESSARY	107.30	-
2	FRONT DOOR HINGE LH @\$73.20	NOT NECESSARY	146.40	-
1	FRONT DOOR INNER LOCK LH	NOT NECESSARY	534.70	-
1	FRONT DOOR INNER TRIM LH	NOT NECESSARY	890.20	-
1	FRONT DOOR LOCK CATCHER LH	NOT NECESSARY	30.40	-
1	FRONT DOOR WEATHER STRIP LH	NOT NECESSARY	171.20	-
1	FRONT DOOR POWER WINDOW MOTOR LH	NOT NECESSARY	679.80	-
1	FRONT DOOR PILLAR LH	TO REPAIR SEE LABOUR	1,352.90	-
1	FRONT FENDER LH	DENTED	747.10	747.10
1	FRONT FENDER INNER GARNISH LH	NOT NECESSARY	108.00	-
1	FRONT FENDER SUPPORT BRACKET LH	NOT NECESSARY	59.80	-
1	FRONT FENDER LAMP LH	CRACKED	42.30	42.30
1	FRONT FENDER UPPER CORNER GARNISH LH	NOT NECESSARY	58.40	-
1	FRONT FENDER INNER COWLING LH	NOT NECESSARY	179.80	-
1	SIDE MIRROR	DAMAGED	1,276.90	1,276.90
	LESS 10% DISCOUNT		-828.42	-
	LESS 25% DISCOUNT		-	-991.33
			7,455.78	2,973.97
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR SEALANT LH (SN)	NOT NECESSARY	150.00	-
1	SET FRONT DOOR INNER TRIM CLIP LH (SN)	NOT NECESSARY	60.00	-
1	SET FRONT DOOR LTA SETICKER (SN)	NECESSARY	40.00	40.00
1	SET FRONT FENDER INNER COWLING CLIP LH (SN)	NOT NECESSARY	80.00	-
			330.00	40.00
<u>LABOUR</u>				
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR LH.		1,400.00	500.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	500.00
	TUFF COAT.		250.00	50.00

Report Ref No. CS/INC22009260/Any3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	REMOVE & REFIX AUDIO SPEAKER.	NOT NECESSARY	120.00	-
	TRANSFER FRONT DOOR MECHANISM LH.		80.00	40.00
	REMOVE & REINSTALL FRONT WINDOW GLASS LH.		80.00	40.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			3,660.00	1,160.00
GRAND TOTAL			11,445.78	4,173.97

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,300.00
---	--	--	-----------------

Report Ref No. CS/INC22009260/Any3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.