

APP. REC. BY: 602MSG
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

30001484645

Claims No.

259884

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Cár / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/07/21 @ 11.29am revised to Nor Azian via Merimen.

18/11/21 Submit Preli. report. - vehicle has not send in for repair

Date/Time, File Pass to?

1) 18/11 Typist

Date/Time, File Return to?

2)

Report Forwarded:

Lump Sum / M/s:

☒ : Preli. Report☐ : Final Report

MER-TP

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Asst Insp (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Other:

TOTAL

CBR 150 RR FBS 65 P5R

- ① ~~Outlet~~ ~~Over~~ \$ 19.00 ✓ Cut
- ② ~~Left~~ Foot Rest Bracket \$ 49.80 ?
- ③ ~~Left~~ Mirror \$ 55.00 ✓ Cut
- ④ Balancing ~~left~~ handle Bar \$ 22.00 ✓ Cut
- ⑤ Right Front Faring \$ 185.00 ✓ Cut
- ⑥ Right Headlamp \$ 435.00 ✓ Cut
- ⑦ ~~left~~ Signal light \$ 48.00 ✓ Cut
- ⑧ Fork alignment \$ 180.00

Total \$ 993.80

labour \$180 - 150.

without Labour Only
2 days.

Guo Qiang (UKK)

82880282

22/7/2021

pat by pat
before repair photos.
After repair photos.

MOTOR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____