3/22/23, 12:40 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22009263/APA3Q2

22/03/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7990000101 **Claimant Vehicle** SND1217Z Insured Vehicle No: SMP2938T

No:

Date of Loss: 14/09/2022 Nature of Claim: TP Claim No: 7742742264SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SND1217Z

AUDI Q7, 2.0 TFSI QU (A) CYR105194 Make & Model: Engine No:

Reg. Date: 06/12/2021 (Man. Year: 2021) Chassis No: WAUZZZ4M0ND006828

Colour: White Odometer: 8051 km

Engine Capacity: 1984 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R19 255/55 R19 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,121.80	11,283.68	3,838.12	25.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,092.00	3,962.00	4,130.00	51.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,213.80	15,245.68	7,968.12	34.32
+ GST 8.00/8.00% (S\$)	1,857.10	1,219.65	637.45	34.33
Nett Amount (S\$)	25,070.90	16,465.33	8,605.57	34.32
+ Loss of Use (6.0 x \$	+ Loss of Use (6.0 x S\$100.00/day) (S\$)			
+ Doc/Search Fee (S\$)		7.45		

Nett Liability (S\$)

INSPECTION

Date of Assignment: 30/09/2022

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1 Date Inspected: 30/09/2022 Inspected At:

Singapore 408699

17,072.78

Estimated Period of Repair: 5.0 days

ADRIAN LING CHEW HSIAO TONG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Dented	5,466.00 FS	*4,372.80 FS
2	1		*FRONT OUTER DOOR SEAL -RH	Necessary	282.00 FS	*225.20 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*FRONT DOOR CATCH -RH	Not Necessary	137.00 FS	*- FS
7	1		*FRONT DOOR COVER-RH	Necessary	963.00 FS	*770.00 FS
8	1		*REAR DOOR -RH	Dented	5,708.00 FS	*4,566.40 FS
9	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
10	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
11	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
12	1		*REAR DOOR CATCH -RH	Not Necessary	137.00 FS	*- FS
13	1		*REAR OUTER DOOR SEAL -RH	Necessary	213.00 FS	*170.40 FS
14	1		*REAR DOOR SILL PANEL WEATHERSTRIP -RH	Not Necessary	282.00 FS	*- FS
15	1		*REAR DOOR COVER-RH	Necessary	883.00 FS	*706.00 FS
16	1		*SUNDRIES	Necessary	400.00 FS	*90.08 FS
17	1		*REAR DOOR ARCH TRIM -RH	Necessary	160.40 FS	*160.40 FS
18	1		*REAR DOOR SEAL -RH	Necessary	222.40 FS	*222.40 FS
⊢=⊢ra	ancnise	part. S=SpcN	NEIT.	Total Parts (S\$)	15,121.80	11,283.68
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO SPRAY RHS REAR DOOR WHEEL ARCH TRIM	New	800.00	150.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES .INSPECT FOR DAMAGES	New	900.00	720.00
3	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,700.00	1,200.00
4	TO RESPRAY RHS FRONT DOOR ,RHS REAR DOOR ,DOOR HANDLE AND TWO DOOR COVERS	New	3,500.00	1,700.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		8,092.00	3,962.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >