

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009264/UPA3Q2**Date:** 07/12/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002005766
Claimant Vehicle No :	SBP20J	Insured Vehicle No :	SGU3668K
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	202222006859

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBP20J	Engine No:	27194130762386
Make & Model:	MERCEDES-BENZ E200ML, 1.8 (A)	Chassis No:	WDB2110422A966029
Reg. Date:	28/06/2006 (Man. Year: 2006)	Odometer:	125774 km
Colour:	Grey		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,120.30	2,155.30	965.00	30.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	770.00	1,060.00	57.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,950.30	2,925.30	2,025.00	40.91
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	4,950.30	2,300.00	2,650.30	53.54
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,547.45		

INSPECTION

Date of Assignment:	20/09/2022		
Date Inspected:	21/09/2022	Inspected At:	Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59 Singapore 408717
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2022)
Parts: 143	MERCEDES-BENZ E200ML 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SBP20J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cracked	1,520.00 FN	*1,520.00 FN
2	1		*REAR BUMPER INNER BRACKET	Twisted	210.00 FN	*210.00 FN
3	1		*REAR BUMPER CENTER PROTECTOR WITH CHROME	Necessary / Scratched	387.00 FN	*387.00 FN
4	1		*REAR BUMPER REINFORCEMENT	Repair	850.00 FN	*- FN
5	1		*SET REVERSE SENSOR	Shorted	450.00 FS	*250.00 FS
						F=Franchise part. S=SpcNett. N=NettItemDisc.
					Sub Total (S\$)	3,417.00 2,367.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	296.70 211.70
					Total Parts (S\$)	3,120.30 2,155.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY FITTINGS AND INSTALL REVERSE SENSOR	New	150.00	50.00
2	TO REPLACE AND ALIGN ABOVE ITEMS TO RESTORE REAR END PANEL INCLUDE KNOCKING AND WELDING	New	750.00	300.00
3	TO SPRAY PAINT REAR REAR BUMPER ,BUMPER , PROTECTOR AND END PANEL	New	850.00	400.00
4	TO CARRY OUT WIRE CHECKING	New	80.00	20.00
Gross Labour Cost (\$\$)			1,830.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >