

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22009268/EVCE2**Date:** 04/05/2023REFERENCE

Insured/Claimant:	TAN PENG CHEOK	Policy No:	2100488912	
Date of Loss:	16/09/2022	Nature of Claim:	OD	Claim No: 7762839754SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDR318S		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)	Engine No:	CZC576661
Reg. Date:	10/11/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V3G1113363
Colour:	Black	Odometer:	65101 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,524.00	20,944.96	18,579.04	47.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,974.00	18,159.00	10,815.00	37.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	68,498.00	39,103.96	29,394.04	42.91
Approved Total (Overridden) (S\$)		39,000.00		
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	67,948.00	38,450.00	29,498.00	43.41
+ GST 8.00/8.00% (S\$)	5,435.84	3,076.00	2,359.84	43.41
Nett Amount (S\$)	73,383.84	41,526.00	31,857.84	43.41

INSPECTION

Date of Assignment:	21/09/2022		
Date Inspected:	20/09/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	23.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR -RH	Dented	3,265.00 FS	*2,612.00 FS
2	1	*REAR OUTER DOOR SEAL -RH	Necessary	179.00 FS	*142.80 FS
3	1	*BONDING AGENT	Necessary	51.00 FS	*40.56 FS
4	1	*CLEANING SOLUTION	Necessary	74.00 FS	*58.96 FS
5	1	*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1	*REAR DOOR CATCH -RH	Not Necessary	105.00 FS	*- FS
7	1	*REAR DOOR INNER SEAL -RH	Crushed	213.00 FS	*170.40 FS
8	1	*REAR DOOR ATTACHMENT PARTS	Not Necessary	134.00 FS	*- FS
9	1	*REAR DOOR HANDLE -RH	Repair	398.00 FS	*- FS
10	1	*REAR DOOR SLIDE VALVE -RH	Not Necessary	25.00 FS	*- FS
11	1	*REAR DOOR HOUSING -RH	Not Necessary	58.00 FS	*- FS
12	1	*REAR DOOR MOUNTING BAR- RH	Not Necessary	182.00 FS	*- FS
13	1	*REAR DOOR BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
14	1	*REAR DOOR BOWDEN CABLE HOLDER	Not Necessary	4.00 FS	*- FS
15	1	*REAR DOOR LOCK -RH	Not Necessary	630.00 FS	*- FS
16	1	*REAR DOOR STRIKER	Not Necessary	69.00 FS	*- FS
17	1	*REAR DOOR BOWDEN CABLE	Not Necessary	43.00 FS	*- FS
18	1	*REAR WINDOW GUIDE -RH	Not Necessary	467.00 FS	*- FS
19	1	*REAR WINDOW GUIDE TRIM STRIP -RH	Not Necessary	250.00 FS	*- FS
20	1	*REAR WINDOW SLOT SEAL TRIM STRIP -RH	Not Necessary	331.00 FS	*- FS
21	1	*REAR DOOR PANEL INNER COVER-RH	Not Necessary	28.00 FS	*- FS
22	1	*REAR DOOR PANEL -RH	Not Necessary	1,831.00 FS	*- FS
23	1	*REAR DOOR WINDOW FRAME TRIM -RH	Not Necessary	134.00 FS	*- FS
24	1	*REAR WINDOW REGULATOR -RH	Bent	286.00 FS	*228.40 FS
25	1	*REAR WINDOW GUIDE RAIL -RH	Not Necessary	58.00 FS	*- FS
26	1	*REAR DOOR CONTROL UNIT	Not Necessary	443.00 FS	*- FS
27	1	*REAR WINDOW REGULATOR MOTOR -RH	Not Necessary	300.00 FS	*- FS
28	1	*REAR SIDE PANEL -RH	Dented	3,662.00 FS	*2,929.60 FS
29	1	*REAR WHEEL HOUSING LINER	Crushed	260.00 FS	*208.00 FS
30	1	*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	93.00 FS	*51.44 FS
31	1	*REAR WINDOW	Necessary	905.00 FS	*724.00 FS
32	1	*REAR WINDOW PRIMER	Necessary	22.00 FS	*17.36 FS
33	1	*REAR SIDE WINDOW -RH	Necessary	635.00 FS	*508.00 FS
34	1	*REAR SIDE WINDOW PRIMER	Necessary	22.00 FS	*17.36 FS
35	1	*REAR WHEEL HOUSING INNER -RH	Not Necessary	673.00 FS	*- FS
36	1	*C-PILLAR PLATE -LOWER	Not Necessary	15.00 FS	*- FS
37	1	*C-PILLAR LOWER REINFORCEMENT -RH	Not Necessary	211.00 FS	*- FS
38	1	*C-PILLAR THREADED PLATE -RH	Not Necessary	36.00 FS	*- FS
39	1	*C-PILLAR PLATE -LOWER	Not Necessary	15.00 FS	*- FS
40	1	*C-PILLAR SIDE MEMBER-RH	Not Necessary	434.00 FS	*- FS
41	1	*REAR WHEEL HOUSING TRIM -RH	Crushed	149.00 FS	*119.20 FS
42	1	*ROOF LINER	Crushed	2,113.00 FS	*1,690.40 FS
43	1	*HEAD AIRBAG UNIT	Broken	2,069.00 FS	*1,655.20 FS
44	1	*BACKREST COVER-RH (FRT RH)	Broken	2,449.00 FS	*1,959.20 FS
45	1	*SIDE AIRBAG UNIT	Broken	1,688.00 FS	*1,350.40 FS
46	2	*THREE -POINT AUTOMATIC SEAT BELT -LH/RH	Jammed	2,454.00 FS	*1,963.20 FS
47	2	*SEAT BELT HEIGHT ADJUSTER -LH/RH	Necessary	430.00 FS	*344.00 FS
48	1	*AIRBAG CONTROL UNIT	Necessary	1,923.00 FS	*1,538.40 FS
49	1	*AIRBAG CRASH SENSOR	Not Necessary	449.00 FS	*- FS
50	2	*FRONT GRAB HANDLE -LH /RH	Not Necessary	326.00 FS	*- FS
51	2	*REAR GRAB HANDLE -LH/RH	Not Necessary	326.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*REAR ALUMINIUM RIM -RH	Cut	1,303.00 FS	*1,042.40 FS
53	1	*REAR ALUMINIUM RUBBER VALVE -RH (2PCS)	Necessary (1 Pc Only)	8.00 FS	*2.96 FS
54	1	*REAR CROSS MEMBER	Not Necessary	1,844.00 FS	*- FS
55	2	*REAR CROSS MEMBER -FRONT	Not Necessary	200.00 FS	*- FS
56	2	*REAR CROSS MEMBER -REAR	Not Necessary	200.00 FS	*- FS
57	1	*REAR WHEEL BEARING HOUSING -RH	Not Necessary	666.00 FS	*- FS
58	1	*REAR WHEEL BEARING HOUSING BONDED RUBBER BUSH	Not Necessary	31.00 FS	*- FS
59	1	*REAR WHEEL BEARING ASSEMBLY PARTS	Not Necessary	486.00 FS	*- FS
60	1	*REAR TRACK ROD -RH	Not Necessary	119.00 FS	*- FS
61	1	*REAR LOWER ARM -RH	Not Necessary	347.00 FS	*- FS
62	1	*REAR WISHBONE -RH	Not Necessary	300.00 FS	*- FS
63	1	*BONDED RUBBER BUSH	Not Necessary	31.00 FS	*- FS
64	2	*REAR UPPER WISHBONE -LH/RH	Not Necessary	300.00 FS	*- FS
65	1	*REAR GAS SHOCK ABSORBER -RH	Not Necessary	276.00 FS	*- FS
66	1	*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
67	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
68	1	*STONE CHIPS	Necessary	180.00 FS	*180.00 FS
69	1	*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
70	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
71	1	*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
72	1	*SUNDRIES	Necessary	900.00 FS	*127.76 FS
73	1	*A-PILLAR TRIM-RH (Supplementary)	Broken	182.00 FS	*145.60 FS
74	1	*FUEL FLAP THROTTLE CONTROL ELEMENT (Supplementary)	Necessary	79.00 FS	*68.96 FS
75	1	*FUEL INSERT (Supplementary)	Broken	188.00 FS	*148.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 39,524.00 20,944.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES RENEW ACCORDING TO DAMAGES	New	360.00	360.00
2	TO CARRY OUT FIRST MEASUREMENT ON CAR -O-LINER	New	800.00	800.00
3	TO REMOVE AND REINSTALL CENTER CONSOLE RENEW SEAT BELTS AND CONTROL UNIT ,PILLAR TRIMS ,ROOF LINING RHS CURTAIN AIRBAG ,RHS DRIVER SIDE AIRBAG AND LEATHER COVER	New	2,800.00	2,800.00
4	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE THE RENEWAL OF RHS REAR FENDER	New	600.00	600.00
5	TO RENEW SOLAR FILM FOR AFFECTED GLASSES (NPA)	New	0.00	0.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS	New	200.00	150.00
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
8	TO REMOVE AND REINSTALL REAR SEAT ,BACK REST HAT TRAY ,LUGGAGE COMPARTMENT TRIMS	New	1,400.00	1,400.00
9	TO REMOVE AND RENEW RHS REAR SUSP ASSY WITH SUBFRAME	New	2,400.00	0.00
10	TO SET UP AND PLACE VEHICLE ON CAR-O-LINER	New	2,400.00	2,400.00
11	TO DISMANTLE REAR BUMPER ,RENEW RHS REAR DOOR ,CUT OUT AND WELD RHS REAR FENDER ,INNER C-PILLAR-REINFORCEMENT ,RHS OUTER WHEEL HOUSE AND SILL PANEL RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	8,400.00	3,500.00
12	TO REMOVE AND REINSTALL RHS FRONT DOOR WING MIRROR ASSY	New	280.00	280.00
13	TO RESPRAY RHS FRONT AND REAR DOORS ,RHS REAR FENDER INNER PANELS ,RHS SILL PANEL ,ROOF CHANNEL DRAIN CHANNEL ,DOOR ENTRANCE AND REAR END PANELLING TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,250.00	3,025.00
14	TO RENEW RHS REAR RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
16	TO REMOVE AND RENEW REAR SEAT BACKREST (Supplementary)	New	780.00	780.00
Gross Labour Cost (\$\$)			28,974.00	18,159.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >