

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22009269/EVCE2**Date:** 31/01/2023**REFERENCE**

Insured/Claimant:	YAP ZONG XING, ERIC	Policy No:	7210154384	
Date of Loss:	16/09/2022	Nature of Claim:	OD	Claim No: 1790795769SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM5128J		
Make & Model:	AUDI A5 SPORTBACK, 2.0 TFSI QUATTRO (A)	Engine No:	DEM034426
Reg. Date:	28/12/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF5XNA002843
Colour:	White	Odometer:	13146 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$213,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,325.00	29,001.44	14,323.56	33.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,192.00	11,332.00	6,860.00	37.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,517.00	40,333.44	21,183.56	34.44
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	60,717.00	39,533.44	21,183.56	34.89
+ GST 8.00/8.00% (S\$)	4,857.36	3,162.68	1,694.68	34.89
Nett Amount (S\$)	65,574.36	42,696.12	22,878.24	34.89

INSPECTION

Date of Assignment:	21/09/2022	
Date Inspected:	20/09/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	11.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,493.00 FS	*1,994.40 FS
2	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	219.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	293.00 FS	*- FS
4	1		*RADIATOR GRILLE STRIKER PLATE	Broken	293.00 FS	*234.00 FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	151.00 FS	*- FS
6	1		*FRONT BUMPER OUTER GRILLE HOLE COVER -LH	Not Necessary	54.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	151.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE TRIM COVER -RH	Not Necessary	54.00 FS	*- FS
9	1		*FRONT BUMPER TRIM -CENTER	Not Necessary	127.00 FS	*- FS
10	1		*RADIATOR GRILLE	Broken	1,881.00 FS	*1,504.80 FS
11	1		*360 CAMERA COVER	Cut	141.00 FS	*112.40 FS
12	1		*360 CAMERA SECURING PLATE	Broken	12.00 FS	*9.28 FS
13	1		*FRONT CAMERA	Cut	1,264.00 FS	*1,011.20 FS
14	1		*FRONT CAMERA ADAPTER CABLE	Not Necessary	219.00 FS	*- FS
15	1		*FRONT CAMERA ADAPTER CABLE LOOM	Not Necessary	319.00 FS	*- FS
16	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	163.00 FS	*130.40 FS
17	1		*LOCK CARRIER BRACKET	Broken	154.00 FS	*122.80 FS
18	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
19	2		*LOCK CARRIER SUPPORT -LH/RH	Necessary	64.00 FS	*51.04 FS
20	1		*360 CAMERA BRACKET	Broken	19.00 FS	*14.64 FS
21	1		*FRONT BUMPER TOP COVER	Crushed	143.00 FS	*114.00 FS
22	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
23	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
24	2		*FRONT FENDER -LH/RH	Dented	2,378.00 FS	*1,902.40 FS
25	2		*FRONT FENDER ATTACHMENT PARTS -LH/RH	Not Necessary	110.00 FS	*- FS
26	2		*FRONT FENDER CLOSING ELEMENT -LH/RH	Not Necessary	166.00 FS	*- FS
27	1		*FRONT FENDER BRACKET -LH/RH	O/S Necessary	82.00 FS	*32.72 FS
28	10		*FRONT FENDER RIVET	Necessary	38.00 FS	*30.40 FS
29	2		*FRONT FENDER BRACE LH/RH	Not Necessary	264.00 FS	*- FS
30	2		*FRONT FENDER LEDGE COVER -LH /RH SHORT	Broken	36.00 FS	*27.84 FS
31	2		*FRONT FENDER UPPER SEAL -LH/RH LONG	Necessary	80.00 FS	*62.88 FS
32	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
33	1		*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
34	3		*BONNET IMPACT PROTECTION -CENTER /RH/LH	Necessary	93.00 FS	*73.20 FS
35	2		*BONNET HINGE -LH/RH	Bent	932.00 FS	*744.80 FS
36	2		*BONNET LOCK -LH/RH	Bent	455.00 FS	*364.00 FS
37	2		*BONNET STIKER -LH/RH	Bent	112.00 FS	*89.12 FS
38	1		*BONNET BOWDEN CABLE -CENTER	Bent	64.00 FS	*50.56 FS
39	1		*BONNET SOUND ABSORBER	Not Necessary	382.00 FS	*- FS
40	1		*BONNET BOWDEN CABLE -CENTER	Not Necessary	64.00 FS	*- FS
41	2		*HEADLIGHT -LH/RH	Broken	16,344.00 FS	*13,075.20 FS
42	1		*HEADLIGHT POWER MODULE	Not Necessary	850.00 FS	*- FS
43	2		*LIFT CYLINDER -LH/RH	Not Necessary	434.00 FS	*- FS
44	2		*LIFT CYLINDER BRACKET-LH/RH	Necessary	34.00 FS	*12.88 FS
45	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
46	1		*LOCK CARRIER MOUNTING	Broken	1,478.00 FS	*901.60 FS
47	2		*RADIATOR AIR GUIDE -LH/RH INNER	Broken	72.00 FS	*56.80 FS
48	2		*RADIATOR AIR GUIDE -LH/RH OUTER	Broken	38.00 FS	*29.28 FS
49	1		*RADIATOR AIR GUIDE -UPPER	Not Necessary	19.00 FS	*- FS
50	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
51	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	64.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*A/C CONDENSER	Dented	683.00 FS	*546.00 FS
53	1		*A/C REFRIGERANT PRESSURE SENSOR	Not Necessary	206.00 FS	*- FS
54	1		*A/C SERVICE VALVE CORE	Not Necessary	53.00 FS	*- FS
55	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
56	1		*CHARGE AIR COOLER SEAL RING	Not Necessary	95.00 FS	*- FS
57	1		*RADIATOR	Bent	699.00 FS	*558.80 FS
58	2		*RADIATOR SECURING PIN-UPPER LH/RH	Not Necessary	6.00 FS	*- FS
59	2		*RADIATOR SLEEVE -UPPER LH/RH	Not Necessary	19.00 FS	*- FS
60	2		*RADIATOR GROMMET -UPPER LH/RH	Not Necessary	22.00 FS	*- FS
61	2		*RADIATOR RUBBER BUSH -LOWER LH/RH	Necessary	20.00 FS	*15.84 FS
62	2		*RADIATOR RUBBER BUSH -LOWER LH/RH	Necessary	28.00 FS	*22.08 FS
63	4		*READY -MIX COOLANT	Necessary	198.00 FS	*237.12 FS
64	2		*FRONT FENDER CHROME TRIM -LH/RH	Necessary	342.00 FS	*272.80 FS
65	2		*FRONT DOOR CHROME TRIM -LH/RH	Necessary	342.00 FS	*272.80 FS
66	2		*FRONT WINDOW SLOT SEAL TRIM STRIP -LH/RH	Not Necessary	892.00 FS	*- FS
67	1		*FRONT NO PLATE	Missing	100.00 FS	*100.00 FS
68	1		*SUNDRIES	Necessary	800.00 FS	*124.16 FS
69	2		*REINFORCEMENT BEAM BRACKET-LH/RH (supplementary)	Bent	508.00 FS	*406.40 FS
70	2		*HEADLIGHT COVER-LH/RH (supplementary)	Necessary	98.00 FS	*77.28 FS
71	1		*AIR INTAKE AIR GUIDE-UPPER (supplementary)	Broken	61.00 FS	*48.48 FS
72	1		*AIR INTAKE AIR DUCT (supplementary)	Broken	25.00 FS	*19.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	43,325.00	29,001.44
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS FOG LAMPS,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY ,FRONT PARKING AID AND FRONT CAMERA ASSY	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER ,RADIATOR AND CHARGES AIR COOLER ,RENEW IF NECESSARY ,CHECK ELECTRICAL FANS AND CONTROL UNIT ,TO PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,BOTH FRONT FENDERS ,BONNET AND BOTH HEADLIGHTS .RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	6,400.00	3,500.00
6	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS AND WING MIRROR ASSY FOR BOTH DOORS REPAIR RENEW BOTH FRONT DOOR WINDOW SLOT SEAL	New	720.00	560.00
7	TO RESPRAY FRONT BUMPER BOTH FRONT FENDERS ,BONNET HINGES ,BOTH A-PILLARS AND BOTH FRONT DOORS	New	6,800.00	3,300.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			18,192.00	11,332.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >