

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22009270/EQCE2**Date:** 04/01/2023**REFERENCE**

Insured/Claimant:	LUO DANNI	Policy No:	7210091715-01	
Date of Loss:	16/09/2022	Nature of Claim:	OD	Claim No: 3932790722SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB4607Y	Engine No:	DEM032932
Make & Model:	AUDI A5, 2.0 SPORTBACK QUATTRO (A)	Chassis No:	WAUZZZF55MA052788
Reg. Date:	24/08/2021 (Man. Year: 2021)	Odometer:	22541 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$207,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 4 mm	Rear Left Side:	Hankook 4 mm
Front Right Side:	Hankook 4 mm	Rear Right Side:	Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,827.00	18,448.08	10,378.92	36.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,792.00	12,667.00	6,125.00	32.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,619.00	31,115.08	16,503.92	34.66
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	46,019.00	29,515.08	16,503.92	35.86
+ GST 7.00/7.00% (S\$)	3,221.33	2,066.06	1,155.27	35.86
Nett Amount (S\$)	49,240.33	31,581.14	17,659.19	35.86

INSPECTION

Date of Assignment:	21/09/2022	
Date Inspected:	20/09/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,493.00 FS	*- FS
2	1		*FRONT BUMPER SIDE SENSOR	Not Necessary	266.00 FS	*- FS
3	6		*FRONT SENSOR SEAL RING	Not Necessary	15.00 FS	*- FS
4	1		*FRONT FENDER -LH	Dented	1,189.00 FS	*951.20 FS
5	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
6	1		*FRONT FENDER CLOSING ELEMENT -LH	Necessary	83.00 FS	*65.84 FS
7	1		*FRONT FENDER BRACKET -LH FRONT	Not Necessary	65.00 FS	*- FS
8	2		*FRONT FENDER BRACKET -LH CENTER	Not Necessary	79.00 FS	*- FS
9	1		*FRONT FENDER BRACE -LH	Not Necessary	132.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE -LH	Not Necessary	41.00 FS	*- FS
11	6		*FRONT FENDER RIVET	Necessary	23.00 FS	*18.24 FS
12	1		*FRONT FENDER TOP COVER -LH FRONT	Necessary	18.00 FS	*13.92 FS
13	1		*FRONT FENDER TOP COVER -LH OUTER	Necessary	40.00 FS	*31.44 FS
14	1		*FRONT WHEEL SPOILER -LH	Not Necessary	82.00 FS	*- FS
15	1		*FRONT FENDER CHROME TRIM -LH	Necessary	171.00 FS	*136.40 FS
16	1		*FRONT DOOR -LH	Dented	3,977.00 FS	*3,181.60 FS
17	1		*FRONT DOOR OUTER SEAL -LH	Necessary	247.00 FS	*197.20 FS
18	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
19	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
20	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
21	1		*FRONT DOOR CHROME TRIM -LH	Necessary	171.00 FS	*136.40 FS
22	1		*FRONT DOOR CATCH -LH	Not Necessary	134.00 FS	*- FS
23	1		*FRONT DOOR HANDLE TRIM -LH	Cut	98.00 FS	*77.92 FS
24	1		*FRONT DOOR HANDLE EXTERIOR -LH	Not Necessary	47.00 FS	*- FS
25	1		*FRONT DOOR HANDLE HOUSING -LH	Not Necessary	9.00 FS	*- FS
26	1		*FRONT DOOR HANDLE MOUNTING BAR-LH	Not Necessary	183.00 FS	*- FS
27	1		*FRONT WINDOW REGULATOR -LH	Not Necessary	392.00 FS	*- FS
28	1		*SIDE MIRROR MOUNTING -LH	Cut	2,137.00 FS	*1,709.60 FS
29	1		*SIDE MIRROR COVER -LH	Repair	308.00 FS	*- FS
30	1		*REAR DOOR -LH	Dented	3,977.00 FS	*3,181.60 FS
31	1		*DOOR BOLTS	Not Necessary	20.00 FS	*- FS
32	1		*REAR DOOR OUTER SEAL -LH	Necessary	247.00 FS	*197.20 FS
33	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
34	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
35	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
36	1		*REAR DOOR CATCH -LH	Not Necessary	134.00 FS	*- FS
37	1		*SIDE MEMBER TRIM -LH	Cut	916.00 FS	*732.40 FS
38	1		*SET ATTACHMENT PARTS	Necessary	136.00 FS	*108.80 FS
39	1		*SET OF ADHESIDE TAPE	Necessary	221.00 FS	*176.80 FS
40	1		*REAR FENDER -LH	Dented	4,076.00 FS	*3,260.80 FS
41	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	299.00 FS	*- FS
42	1		*SET ATTACHMENT FOR WHEEL LINER	Not Necessary	176.00 FS	*- FS
43	1		*FRONT FENDER STONE CHIP GUARD -LH	Cut	57.00 FS	*45.28 FS
44	3		*STONR CHIP GUARD RIVET	Necessary	6.00 FS	*1.44 FS
45	2		*ALUMINIUM RIM -LH FRONT & LH REAR	Cut	3,778.00 FS	*3,022.40 FS
46	2		*RUBBER VALVE	Necessary	15.00 FS	*2.96 FS
47	1		*TYRE -LH FRONT & LH REAR (2PCS)	Torn (1Pc Only)	760.00 FS	*380.00 FS
48	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
49	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
50	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
51	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
53	1		*FRONT FENDER STONE CHIP GUARD - LH (Supplementary)	Not Necessary	57.00 FS	*- FS
54	1		*HEADLIGHT TOP COVER - LH (Supplementary)	Necessary	49.00 FS	*38.64 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	28,827.00 18,448.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	800.00	800.00
3	TO REMOVE AND REINSTALL REAR SEAT BENCH BACK REST HAT TRAY DISENGAGE CURTAIN AIRBAG	New	1,400.00	1,400.00
4	TO DISLOSGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER ,LHS FRONT AND REAR DOORS AND LHS SIDE MEMBER TRIM ,CUT AND WELD LHS REAR FENDER LOWER SECTION .RENEW ALL DAMAGED TRIMS ,REINSTALL ALL PARTS REMOVED	New	6,800.00	3,750.00
6	TO SPRAY PAINT ON FRONT BUMPER ,LHS FRONT FENDER,LHS FRONT AND REAR DOORS ,DOOR HANDLES ,WING MIRROR COVER ,LHS SIDE MEMBER TRIM ,LHS REAR FENDER ,LHS SILL PANEL AND DOOR ENTRANCE TO CARRY OUT JOINT SEALER WORKS	New	7,400.00	4,325.00
7	TO RENEW LHS FRONT AND REAR RIMS ,CARRY OUT WHEEL ALIGNMENT	New	320.00	320.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			18,792.00	12,667.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >