

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009284/AQY3Q2**Date:** 10/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00025492202

Claimant Vehicle No : SLU2597D **Insured Vehicle No :** GBH6933C

Date of Loss: 15/09/2022 Nature of Claim: TP Claim No: SNM22D206634/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU2597D**

Make & Model: MAZDA 3, 1.5 (A) Engine No: P520452929

Reg. Date: 28/11/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0160511

Colour: Blue Odometer: 79899 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,805.00	2,745.60	1,059.40	27.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,010.00	720.00	41.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,535.00	3,755.60	1,779.40	32.15
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	5,535.00	3,000.00	2,535.00	45.80

INSPECTION

Date of Assignment: 09/11/2022

Date Inspected: 20/09/2022 Inspected At: Best Solution Autocare Pte Ltd (HQ)
53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2022)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU2597D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	985.00 F	*985.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	Cracked	63.00 F	*63.00 FL
3	1		*O/S HEADLAMP	Cracked	1,550.00 F	*1,550.00 FL
4	1		*O/S FOG LAMP	Not Necessary	275.00 F	*- FL
5	1		*O/S FOG LAMP GARNISH	Not Necessary	98.00 F	*- FL
6	1		*O/S FRONT FENDER	Dented	579.00 F	*579.00 FL
7	1		*O/S FENDER INNER SHIELD	Deformed	255.00 F	*255.00 FL
					Sub Total (S\$)	3,805.00 3,432.00
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00 686.40
					Total Parts (S\$)	3,805.00 2,745.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,PANEL BEAT ,REPAIR	New	800.00	500.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	800.00	450.00
3	ANTI RUST	New	50.00	30.00
4	WIRING CHECK	New	80.00	30.00
Gross Labour Cost (\$\$)			1,730.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >