

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009285/KWY3Q2**Date:** 07/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00143892201

**Claimant Vehicle No :** SJZ4553P **Insured Vehicle No :** SMZ425S

Date of Loss: 18/09/2022 Nature of Claim: TP Claim No: SNM22D206689/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJZ4553P**

Make & Model: HONDA JAZZ, 1.3 L (A) Engine No: L13Z11035461

Reg. Date: 26/11/2010 (Man. Year: 2009) Chassis No: JHMGE68509S235435

Colour: Metallic Black Odometer: 142781 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16

Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,738.90	4,635.64	4,103.26	46.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	2,600.00	1,090.00	29.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,428.90</b>	<b>7,235.64</b>	<b>5,193.26</b>	<b>41.78</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,428.90</b>	<b>5,700.00</b>	<b>6,728.90</b>	<b>54.14</b>

**INSPECTION**

Date of Assignment: 06/10/2022

Date Inspected: 20/09/2022 Inspected At: TSR AUTOMOTIVE PTE LTD (HQ)  
160 SIN MING DRIVE, #06-01 SIN MING  
AUTOCITY  
Singapore 575722

Estimated Period of Repair: 10.0 days

**Adjuster:** KENNETH KONG**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2022)
<b>Parts:</b>	144	HONDA JAZZ 1.3 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJZ4553P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	820.00 FL	*762.20 FL
2	1		*TAILGATE CENTER LOGO	Not Necessary	58.00 FL	*- FL
3	1		*SET TAILGATE W/SCREEN MOULDING	Necessary	140.00 FL	*92.30 FL
4	1		*TAILGATE OUTER GARNISH	Mtg Cracked	332.00 FL	*112.30 FL
5	1		*TAILGATE TRIM BOARD	Mtg Cracked	335.00 FL	*282.40 FL
6	1		*TAILGATE LOCK	Dented	220.00 FL	*189.50 FL
7	1		*CENTER LOGO	Necessary	68.00 FL	*28.00 FL
8	1		*JAZZ EMBLEM	Necessary	56.00 FL	*45.00 FL
9	2		*TAILLAMPS	Mtg Cracked	780.00 FL	*598.40 FL
10	1		*TAILLAMP PANELS	N/S Bent	280.00 FL	*140.00 FL
11	2		*TAILLAMP LOWER BRACKETS	Cracked	180.00 FL	*180.00 FL
12	1		*REAR FENDERS (NPA)	Repair	0.00 FL	*- FL
13	2		*REAR FENDER INNER SIDE TRIMS	Buckled / Deformed	980.00 FL	*646.00 FL
14	1		*END PANEL	Bent	350.00 FL	*296.80 FL
15	1		*END PANEL TOP GARNISH	Dented	225.00 FL	*80.20 FL
16	1		*END PANEL TOP LATCH	Repai	68.00 FL	*- FL
17	1		*SPARE TYRE PANEL	Bent	850.00 FL	*737.00 FL
18	1		*SPARE TYRE TOP BOARD	Distorted	550.00 FL	*183.90 FL
19	1		*SPARE TYRE CENTER TRAY	Deformed	480.00 FL	*114.60 FL
20	1		*SPARE TYRE SIDE TRAY	No such part	664.00 FL	*- FL
21	1		*REAR EXHAUST HEAT SHIELD	Repair	168.00 FL	*- FL
22	1		*REAR EXHAUST	Bent	682.00 FL	*654.50 FL
23	1		*REAR BUMPER	Bent	525.00 FL	*497.70 FL
24	1		*REAR BUMPER SIDE RETAINERS	N/S Distorted	120.00 FL	*60.00 FL
25	2		*REAR BUMPER BRACKETS	No such part	140.00 FL	*- FL
26	2		*T TAILGATE W/SCREEN SEALANT	Necessary	140.00 FS	*40.00 FS
27	1		*SET REAR NO PLATE WIHT FRAME	Serviceable	50.00 FS	*- FS
28	1		*SET REVERSE SENSORS	Serviceable	280.00 FS	*- FS
29	20		*REAR FENDER UNDERSHIELD CLIPS	Not Necessary	70.00 FS	*- FS
30	10		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,646.00</b>	<b>5,775.80</b>
<b>- List Item Discount on L Items 10.00/20.00% (\$\$)</b>	907.10	1,140.16
<b>Total Parts (\$\$)</b>	<b>8,738.90</b>	<b>4,635.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGE TO REPAIR ,REPLACE ,ALIGN ADJUST ,REMOVE & REFIX ACCIDENT AFFECTED AREA	New	1,200.00	1,100.00
2	TO DO ANTI RUST	New	120.00	90.00
3	TO REPLACE SENSOR ,CHECK WIRING SYSTEM FOR REAR	New	120.00	20.00
4	TO REMOVE REFIX GARNISH ,SIDE TRIM ,UPHOLSTERY ,TRIM BOARD ,REFIX CAR SEAT ETC	New	380.00	100.00
5	TO REPLACE REAR EXHAUST	New	160.00	60.00
6	TO DO SEALANT SEAL GAP ,WATERPROOFING ON CUTTING WELDING ACCIDENT AFFECTED AREA	New	250.00	50.00
7	REMOVE REFIX REAR W/SCREEN	New	140.00	120.00
8	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE	New	120.00	60.00
9	TO DO SPRAY PAINTING INNER OUTER AND ACCIDENT AFFECTED AREA	New	1,200.00	1,000.00
<b>Gross Labour Cost (\$)</b>			<b>3,690.00</b>	<b>2,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >