

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009287/UYA3Q2**Date:** 17/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210061148
Claimant Vehicle No :	SMU681U	Insured Vehicle No :	SKP1158H
Date of Loss:	18/09/2022	Nature of Claim:	TP
		Claim No:	2655914513SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU681U	Engine No:	DEM023831
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF40LA063042
Reg. Date:	28/07/2020 (Man. Year: 2020)	Odometer:	21387 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,608.10	24,559.60	28,048.50	53.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,990.00	1,860.00	48.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	56,458.10	26,549.60	29,908.50	52.97
Approved Total (Overridden) (S\$)		21,200.00		
(S\$)	56,458.10	21,200.00	35,258.10	62.45
+ GST 7.00/7.00% (S\$)	3,952.07	1,484.00	2,468.07	62.45
Nett Amount (S\$)	60,410.17	22,684.00	37,726.17	62.45
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		23,386.00		

INSPECTION

Date of Assignment:	21/09/2022	
Date Inspected:	21/09/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	5,055.00 F	*3,425.00 FL
2	1		*BONNET INNER CENTRE SEAL	Necessary	82.00 F	*78.00 FL
3	1		*BONNET INNER SEAL N/S	Necessary	70.00 F	*60.00 FL
4	1		*BONNET INSULATOR	Not Necessary	380.00 F	*- FL
5	1		*SET BONNET INSULATOR CLIPS	Not Necessary	80.00 F	*- FL
6	1		*BONNET INNER LOCK	Twisted	650.00 F	*245.00 FL
7	1		*FRONT BUMPER	Distorted	2,697.00 F	*2,377.00 FL
8	1		*FRONT BUMPER SIDE RETAINERS	N/S Cracked	500.00 F	*115.00 FL
9	1		*FRONT BUMPER CENTRE GRILLE	Twisted	420.00 F	*222.00 FL
10	1		*FRONT BUMPER LOWER CENTRE GRILLE	Twisted	399.00 F	*180.00 FL
11	1		*FRONT BUMPER SPONGE	Torn	416.00 F	*182.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	1,515.00 F	*899.00 FL
13	1		*FRONT BUMPER REINFORCEMENT LOWER BRACKET	Bent	350.00 F	*205.00 FL
14	1		*FRONT BUMPER REINFORCEMENT LOWER	Bent	1,100.00 F	*480.00 FL
15	1		*FRONT BUMPER UNDER COVER	Torn	880.00 F	*425.00 FL
16	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	60.00 F	*45.00 FL
17	1		*FRONT FOG LAMP N/S	Not Necessary	520.00 F	*- FL
18	1		*FRONT FOG LAMP GARNISH N/S	Broken / Missing	335.00 F	*282.00 FL
19	1		*FRONT GRILLE ASSY	Cracked	1,880.00 F	*1,754.00 FL
20	1		*FRONT GRILLE LOGO	Not Necessary	105.00 F	*- FL
21	1		*SET FRONT GRILLE PARKING CAMERA	Not Necessary	1,850.00 F	*- FL
22	1		*HEADLAMPS	N/S Cracked	17,856.00 F	*8,172.00 FL
23	1		*HEADLAMP LOWER BRACKETS	N/S Cracked	1,780.00 F	*168.00 FL
24	1		*HEADLAMP NOZZLE COVER N/S	Twisted	82.00 F	*82.00 FL
25	1		*HEADLAMP NOZZLE N/S	Cracked	350.00 F	*231.00 FL
26	1		*FRONT AIR GUIDE TOP N/S	Torn	98.00 F	*98.00 FL
27	1		*FRONT AIR GUIDE	N/S Torn	870.00 F	*200.00 FL
28	1		*FRONT SUPPORT PANEL TOP COVER	Distorted	199.00 F	*168.00 FL
29	1		*FRONT SUPPORT PANEL	Cracked	1,955.00 F	*1,127.00 FL
30	1		*FRONT SUPPORT PANEL N/S	Bent	100.00 F	*100.00 FL
31	1		*FRONT SUPPORT PANEL CENTRE BRACKET	Bent	150.00 F	*142.00 FL
32	1		*AIR CON CONDENSER	Bent / Twisted	1,540.10 F	*880.00 FL
33	1		*RADIATOR	Not Necessary	988.00 F	*- FL
34	1		*INTER COOLER	Holder Cracked	1,450.00 F	*1,280.00 FL
35	1		*FRONT BRACE PANEL	Twisted	885.00 F	*366.00 FL
36	1		*FRONT FENDER N/S	Buckled	1,200.00 F	*1,200.00 FL
37	1		*FRONT FENDER INNER SHIELD N/S	Torn	313.00 F	*282.00 FL
38	1		*FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
39	1		*FRONT DOOR N/S	Repair	2,880.00 F	*- FL
40	1		*TEMPERATURE SENSOR	Cracked	188.00 F	*188.00 FL
41	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 F	*60.00 FL
42	1		*FRONT LICENCE PLATE W/HOLDER	Bent	150.00 FS	*20.00 FS
43	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS
44	1		*BOL AIR CON OIL	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	52,608.10	25,848.00
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	1,288.40
Total Parts (\$)	52,608.10	24,559.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REFILL AIR CON GAS	New	120.00	100.00
3	TO SPRAY RUST PROOFING	New	100.00	60.00
4	TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM	New	580.00	60.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	800.00
6	TO PUTTY & SPRAY PAINTING	New	1,800.00	950.00
Gross Labour Cost (S\$)			3,850.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >