



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 6405J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (WCP)	DENTED	280.00	280.00
1	FRONT BUMPER RH SIDE RETAINER (WCP)	BROKEN	45.00	45.00
1	FRONT BUMPER RH FOG LAMP GARNISH (WCP)	CUT / DISTORTED	70.00	70.00
6	FRONT BUMPER CLIPS @\$2.00 (WCP)	NECESSARY	12.00	12.00
1	RH HEADLAMP (WCP)	CUT / SCRATCHED	980.00	980.00
1	FRONT RH FENDER (WCP)	DENTED	350.00	350.00
1	FRONT RH FENDER INNER SHIELD (WCP)	TORN	95.00	95.00
6	FRONT RH FENDER INNER SHIELD CLIPS @\$2.00 (WCP)	NECESSARY	12.00	12.00
1	RH HEADLAMP PROTECTOR (WCP)	CUT	70.00	70.00
	COST PLUS 10%		191.40	191.40
			2,105.40	2,105.40
<u>LABOUR</u>				
	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, FRT RH FENDER, TO KNOCK & REPAIR FRT LH FENDER INNER PANEL, FRT SUPPORT PANEL.		500.00	400.00
	PUTTY & RESPRAY FRT RH DOOR, FENDER, FRT BUMPER, FRT RH FENDER INNER PANEL AND ALL AFFECTED AREAS.		700.00	500.00
			1,200.00	900.00
GRAND TOTAL			3,305.40	3,005.40

RECOMMENDED COST OF REPAIRS			3,005.40
LESS EXCESS			-700.00
NETT LIABILITY			2,305.40

Report Ref No. CS6/GAI22009292/Dqy3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.