



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 1998U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE ASSY	TO REPAIR SEE LABOUR	2,697.26	-
1	TAILGATE OUTER (GARNISH)	SERVICEABLE	750.84	-
1	REAR END OUTER PANEL	TO REPAIR SEE LABOUR	470.40	-
1	EMBLEM "RENAULT" REAR	SERVICEABLE	121.32	-
1	TAILGATE LOCK ASSY GS4	SERVICEABLE	137.16	-
1	BUMPER REAR GS4 BOSS	TO REPAIR SEE LABOUR	1,113.60	-
1	REAR BUMPER PAD LOWER (BLACK)	DENTED/CUT	666.36	666.36
1	REAR BUMPER LOWER (SIVER)	SERVICEABLE	579.84	-
1	REAR BUMPER REINFORCEMENT (NPA)	TO REPAIR SEE LABOUR	-	-
2	REAR BUMPER LOWER PAD SUPPORT CTE @\$97.44	SERVICEABLE	194.88	-
1	REAR BUMPER LOWER SUPPORT LH	SERVICEABLE	127.20	-
1	REAR BUMPER LOWER SUPPORT RH	SERVICEABLE	127.20	-
1	REAR BUMPER CENTER GARNISH	SERVICEABLE	399.60	-
1	REAR BUMPER SENSOR HARNESS	SERVICEABLE	231.84	-
4	REAR REVERSE SENSOR @\$291.60	SERVICEABLE	1,166.40	-
1	REAR BUMPER LOWER REFLECTOR LH	SERVICEABLE	415.20	-
	LESS 10% DISCOUNT		-	-66.64
			9,199.10	599.72
<b><u>SPECIAL NETT ITEMS</u></b>				
6	REAR BUMPER CLIPS @\$7.00 (SN)	NOT NECESSARY	42.00	-
			42.00	-
<b><u>LABOUR</u></b>				
	TO PANEL BEATING, REALIGN DISMANTLE REAR BUMPER, REAR BOOT LID, END PANEL, FENDER REAR LH, REAR CHASSIS LH AND ALL NECESSARY ETC. INCLUSIVE OF THE REPAIR OF TAILGATE ASSY, REAR END OUTER PANEL, BUMPER REAR GS4 BOSS AND REAR BUMPER REINFORCEMENT.		1,200.00	200.00

Report Ref No. CS/GAI22009294/Kvy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEM OF REAR SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF REAR TAIL GATE LAMP & TAIL LAMP LH/RH AND FRONT HEADLAMP LH/RH.		120.00	10.00
	TO APPLY TUFF COATING AND SPRAY ANTI RUST PROOFING REAR PORTION AND FRONT PORTION.	NOT NECESSARY	180.00	-
	TO REMOVE & INSTALL LUGGAGE COMPARTMENT AND SIDE FENDER INNER TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO PUTTY & RESPRAY PAINTING REAR BUMPER, REAR BOOT LID, END PANEL, FENDER REAR LH AND ALL NECESSARY ETC.		1,000.00	220.00
			2,620.00	430.00
<b>GRAND TOTAL</b>			<b>11,861.10</b>	<b>1,029.72</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,029.72</b>

Report Ref No. CS/GAI22009294/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.