



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 2043H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	465.30	-
1	SET REAR BUMPER CLIPS	NOT NECESSARY	48.00	-
1	TAILLAMP RH	BROKEN	391.20	391.20
1	CORNER PANEL (CUT)	NOT CONSISTENT WITH THE IMPACT	376.50	-
1	CORNER PANEL BRACKET	NOT NECESSARY	31.50	-
	LESS 25% DISCOUNT		-	-97.80
			1,312.50	293.40
<u>SPECIAL NETT ITEMS</u>				
1	"CORPORATE" ADVERTISEMENT & "FULL WRAP" ARTWORK (SN)	SERVICEABLE	1,800.00	-
			1,800.00	-
<u>LABOUR</u>				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	20.00
	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR.	NOT NECESSARY	120.00	-
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.		400.00	400.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		600.00	200.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	NOT NECESSARY	80.00	-
			1,250.00	620.00
GRAND TOTAL			4,362.50	913.40
RECOMMENDED COST OF REPAIRS				913.40

Report Ref No. CS/SMO22009295/Uwy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.