



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009295/Uwy3e2	
			Date: 05/10/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 90M	Veh. Inspected	GBF 2043H
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203337/LOR	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	21/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDH2015021526	Colour	WHITE
	Odometer	407896 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	AUSTONE	6 mm
	L/H Front Tyre	195 R15	AUSTONE	6 mm
	R/H Rear Tyre	195 R15	AUSTONE	6 mm
	L/H Rear Tyre	195 R15	AUSTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/09/2022	Inspection Date	21/09/2022
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	