

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22009298/UNY3E2**Date:** 06/10/2022**REFERENCE**

Insured/Claimant: SULAIMAN BIN MOOSA Policy No: D21MPC0003429_01
Date of Loss: 19/09/2022 Nature of Claim: OD Claim No: MPC2022D0005351

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDQ971K**
Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 1ZRX562523
Reg. Date: 09/06/2016 (Man. Year: 2016) Chassis No: MR053REH104548661
Colour: Pearl White Odometer: 33224 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$54,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,672.40	1,789.05	883.35	33.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,380.00	1,040.00	30.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,092.40	4,169.05	1,923.35	31.57
Approved Total (Overridden) (S\$)		3,300.00		
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
Nett Amount (S\$)	4,992.40	2,200.00	2,792.40	55.93

INSPECTION

Date of Assignment: 21/09/2022
Date Inspected: 21/09/2022 Inspected At: Hup Motor Trading & Service (HQ)
Estimated Period of Repair: 6.0 days Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Sep 2022)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDQ971K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	620.60 FL	*620.60 FL
2	10		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
3	1		*REAR BUMPER N/S TOP RETAINER	Cracked	65.60 FL	*65.60 FL
4	1		*REAR BUMPER N/S SIDE RETAINER	Cracked	118.70 FL	*118.70 FL
5	1		*REAR BUMPER N/S SIDE BRACKET CLIPS	Necessary	4.80 FL	*4.80 FL
6	1		*REAR BUMPER N/S WHEEL GUARD GARNISH	Deformed / Torn	59.70 FL	*59.70 FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	432.50 FL	*- FL
8	1		*N/S TAIL LAMP ASSY	Not Necessary	410.80 FL	*- FL
9	2		*N/S TAIL LAMP CLIPS & STOPPER	Not Necessary	9.80 FL	*- FL
10	1		*N/S TAIL LAMP PANEL	Repair	120.50 FL	*- FL
11	1		*REAR N/S FENDER	Badly Dented	1,244.80 FL	*1,244.80 FL
12	1		*REAR N/S FENDER AIRSCOOP GRILLE	Not Necessary	148.00 FL	*- FL
13	6		*REAR N/S FENDER INNER SHIELD CLIPS	Not Necessary	25.20 FL	*- FL
14	5		*REAR N/S FENDER WHEEL GARNISH CLIPS	Not Necessary	21.00 FL	*- FL
15	2		*FUEL TANK LID RIVERT CLIPS & STOPPER	Necessary	13.80 FL	*13.80 FL
16	1		*REAR WINDSCREEN GLASS INNER SHIELD	Necessary	45.40 FL	*45.40 FL
17	1		*REAR WINDSCREEN GLASS INNER DAM RUBBER	Necessary	44.00 FL	*44.00 FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS
19	1		*BODY JOINT SEALANT	Necessary	52.50 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,530.70	2,355.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	858.30	566.35
Total Parts (\$\$)	2,672.40	1,789.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	150.00	120.00
3	TO REMOVE & REFIX FUEL TANK HOSE, PIPE & NECESSARY PARTS	New	150.00	60.00
4	TO REMOVE & REFIX REAR CUSHION SEAT, CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER & NECESSARY PARTS	New	150.00	80.00
5	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,300.00	1,100.00
6	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,500.00	1,000.00
7	TO PUMP BODY SEALANT FOR AFFECTED ACCIDENT PARTS	New	120.00	0.00
Gross Labour Cost (\$\$)			3,420.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >