11/14/22, 1:44 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009302/KWY3Q2

14/11/2022 Date:

REFERENCE

No:

China Taiping Insurance (Singapore) Pte. Policy No: Handling Insurer:

DMCVSNA00111012200

Claimant Vehicle

GBE9943U

Insured Vehicle No:

XE907Z

Date of Loss: 06/09/2022 Nature of Claim: TP Claim No:

SNM22D206386/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE9943U**

Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25393824A

Reg. Date: 17/05/2016 (Man. Year: 2016) Chassis No: JN1MC2E26Z0006445 Odometer: 116895 km

Colour: Grey

Engine Capacity: 2488 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8 Front Left Side: Rear Left Side: Habilead 9 mm Habilead 9 mm Front Right Side: Habilead 9 mm Rear Right Side: Habilead 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,427.74	3,896.72	2,531.02	39.38
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,480.00	1,500.00	980.00	39.52
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,907.74	5,396.72	3,511.02	39.42
	Approved Total (Overridden) (S\$)		4,250.00		
	(S\$)	8,907.74	4,250.00	4,657.74	52.29
	+ GST 7.00/7.00% (S\$)	623.54	297.50	326.04	52.29
	Nett Amount (S\$)	9,531.28	4,547.50	4,983.78	52.29

INSPECTION

Date of Assignment: 21/09/2022

E M Solution Pte Ltd (HQ)

Date Inspected: 26/09/2022 Inspected At: 160 Sin Ming Drive,, #03-18, Sin Ming Autocity

Singapore 575722

Estimated Period of Repair: 6.0 days

KENNETH KONG XinYu Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Nov 2022)

Parts: N/A NISSAN NV350 2.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE9943U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Bent	1,276.40 FN	*1,158.30 FN
2	1		*FRT DOOR OUTER MOULDING RH	Buckled	227.50 FN	*157.80 FN
3	2		*FRT DOOR HINGE TOP & LOWER	Repair	138.20 FN	*- FN
4	1		*FRT DOOR CHECKER RH	Serviceable	48.40 FN	*- FN
5	1		*FRT DOOR REGULATOR GEAR	Distorted	204.70 FN	*155.30 FN
6	1		*FRT DOOR REGULATOR MOTOR	Jammed	663.60 FN	*568.10 FN
7	1		*FRT DOOR INNER TRIM BOARD	Mtg Cracked	544.70 FN	*504.60 FN
8	1		*FRT DOOR WEATHERSTRIP RH	Serviceable	126.30 FN	*- FN
9	1		*FRT DOOR LOWER WEATHERSTRIP RH	Cut	88.50 FN	*88.50 FN
10	1		*FRT DOOR MECHANISM LOCK RH	Repair	186.70 FN	*- FN
11	1		*FRT DOOR LOCK INNER GARNISH RH	Serviceable	22.10 FN	*- FN
12	1		*FRT DOOR WING MIRROR RH	Cracked	520.30 FN	*520.30 FN
13	1		*FRT STEP PANEL GARNISH RH	Serviceable	88.20 FN	*- FN
14	1		*FRT STEP PANEL RH	Bent	125.00 FN	*125.00 FN
15	1		*FRT SIDE PANEL OUTER RH	Bent	627.80 FN	*518.60 FN
16	1		*FRT SIDE PANEL AIR GARNISH	Serviceable	157.30 FN	*- FN
17	1		*FRT DOOR PILLAR ARCH LOWER PANEL RH	Repair	556.30 FN	*- FN
18	1		*FRT DOOR PILLAR LOWER PANEL GARNISH RH	Cracked	94.30 FN	*94.30 FN
19	1		*FRT SHOCK ABSORBER RH	Serviceable	182.80 FN	*- FN
20	1		*FRT LOWER ARM RH	Serviceable	172.30 FN	*- FN
21	1		*FRT KNUCKLE ARM RH	Serviceable	352.10 FN	*- FN
22	1		*FRT WHEEL HUB ASSY	Serviceable	205.10 FN	*- FN
23	1		*FRT ROAD RIM RH	Dented	200.00 FS	*200.00 FS
24	1		*FRT WHEEL COVER RH	Missing	250.00 FS	*165.00 FS
25	1	nort C=Cnol	*FRT DOOR COS STICKER	Necessary	30.00 FS	*30.00 FS
r-r18	incriise	part. 3–3pcN	lett. N=NettItemDisc.	Sub Total (S\$)	7,088.60	4,285.80
			- Nett Item Discount on N Items 1		660.86	389.08
				Total Parts (S\$)	6,427.74	3,896.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	50.00	20.00
2	TO REMOVE & REPLACE UPHOLSTERY ,CUSHION SEAT & TRIM GARNISHES	New	100.00	60.00
3	TO REMOVE,TRANSFER FRT DOOR COMPONENTS	New	100.00	60.00
4	TO REMOVE, REPLACE FRT SUSPENSION UNDERCARRIAGE PARTS	New	350.00	0.00
5	TO REMOVE ,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00
6	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	800.00	600.00
7	RUST PROOFING ON AFFECTED PORTIONS	New	80.00	60.00
	Gross Labour	r Cost (S\$)	2,480.00	1,500.00
	Report was unsubmitted during this pri	int_out		

< END OF ESTIMATES >