

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009305/RVY3Q2**Date:** 18/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00078252205

**Claimant Vehicle
No :** GBB1938D**Insured Vehicle
No :** GW7073P

Date of Loss: 24/08/2022

Nature of Claim: TP

Claim
No: SNM22D206010/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBB1938D**

Make & Model: TOYOTA HIACE, 3.0 D MANUAL (M)

Engine No: 1KD1859444

Reg. Date: 28/08/2008 (Man. Year: 2008)

Chassis No: JTFHT02P800030889

Colour: Grey

Odometer: 485990 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,695.00	2,170.00	525.00	19.48
Miscellaneous Items	85.00	65.00	20.00	23.53
Labour	1,415.40	1,415.40	0.00	0.00
Paintwork Labour	709.15	684.06	25.09	3.54
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,904.55	4,334.46	570.09	11.62
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	4,904.55	3,450.00	1,454.55	29.66
+ GST 7.00/7.00% (S\$)	343.32	241.50	101.82	29.66
Nett Amount (S\$)	5,247.87	3,691.50	1,556.37	29.66

INSPECTION

Date of Assignment: 21/09/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 21/09/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)

6 Marsiling Lane
Singapore 739145

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Nov 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D MANUAL (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB1938D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		2,695.00 F	*2,170.00 F
F=Franchise part.						
Total Parts (S\$)					2,695.00	2,170.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	85.00	65.00
Sub Total (\$)			85.00	65.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	709.15	684.06
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	1,415.40	1,415.40
Gross Labour Cost (\$)			2,124.55	2,099.46

Report was unsubmitted during this print-out.

< END OF ESTIMATES >