

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009308/UVY3Q2**Date:** 17/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00228512102

Claimant Vehicle No : SLL2150G**Insured Vehicle No :** SMK8550P

Date of Loss: 20/09/2022

Nature of Claim: TP

Claim No: SNM22D206736/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLL2150G**

Make & Model: MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)

Engine No: PE20838220

Reg. Date: 17/02/2017 (Man. Year: 2016)

Chassis No: JM6GL1071H0104749

Colour: Grey

Odometer: 96895 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55Z R17

Rear Tyre Size: 225/55Z R17

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,496.20	3,086.60	3,409.60	52.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,440.00	700.00	32.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,636.20	4,526.60	4,109.60	47.59
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	8,636.20	3,600.00	5,036.20	58.31
+ GST 7.00/7.00% (S\$)	604.53	252.00	352.53	58.31
Nett Amount (S\$)	9,240.73	3,852.00	5,388.73	58.31

INSPECTION

Date of Assignment: 21/09/2022

Date Inspected: 03/10/2022 Inspected At:

Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2022)

Parts: 143 MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL2150G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER WITH LOWER (BLACK)	Torn	1,099.00 FL	*1,099.00 FL
2	2		*REAR BUMPER SIDE HOLDER -LH/RH	Necessary	84.00 FL	*84.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	59.00 FL	*59.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	538.00 FL	*538.00 FL
5	1		*SET REAR BUMPER SENSOR	Shorted	624.00 FS	*250.00 FS
6	4		*REAR BUMPER SENSOR COVER	Not Necessary	116.00 FL	*- FL
7	1		*REAR BUMPER SENSOR WIRE	Not Necessary	127.00 FL	*- FL
8	2		*REAR BUMPER TOWING COVER -LH/RH	Deformed / Missing	96.00 FL	*96.00 FL
9	2		*REAR BUMPER REFLECTORS -LH/RH	Not Necessary	98.00 FL	*- FL
10	2		*REAR BUMPER BRACKETS -LH/RH	Twisted	86.00 FL	*86.00 FL
11	1		*REAR PANEL	Repair	606.00 FL	*- FL
12	1		*REAR PANEL TOP GARNISH	Not Necessary	149.00 FL	*- FL
13	1		*REAR BOOT LOCK SENSOR	Not Necessary	213.00 FL	*- FL
14	1		*REAR BOOT	Dented / Bent	1,115.00 FL	*1,115.00 FL
15	1		*REAR BOOT OUTER GARNISH -CHROME	Not Necessary	302.00 FL	*- FL
16	1		*SET REAR BOOT GLASS MOULDING	Not Necessary	106.00 FL	*- FL
17	1		*REAR BOOT TOP LOCK	Bent / Twisted	160.00 FL	*160.00 FL
18	1		*REAR BOOT BOTTOM LOCK	Not Necessary	79.00 FL	*- FL
19	1		*REAR BOOT RUBBER	Twisted	114.00 FL	*114.00 FL
20	1		*REAR BOOT MAZDA LOGO	Necessary	57.00 FL	*57.00 FL
21	1		*REAR BOOT MAZDA 6 LOGO	Necessary	28.00 FL	*28.00 FL
22	1		*REAR BOOT SKYACTIVE LOGO	Necessary	66.00 FL	*66.00 FL
23	1		*REAR EXHAUST PIPE WITH CHROME	Not Necessary	1,486.00 FL	*- FL
24	1		*SET REAR NUMBER PLATE WITH CASING	Scratched	35.00 FS	*35.00 FS
25	1		*SET REAR BOOT CAMERA	Serviceable	350.00 FS	*- FS
26	2		*SEALANT	Not Necessary	40.00 FS	*- FS
27	1		*SPONGE TAPE	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,853.00	3,787.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,356.80	700.40
Total Parts (\$)	6,496.20	3,086.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO TUFF-KOTE	New	60.00	30.00
3	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
4	TO REMOVE ,REFIT REAR GARNISH ,CUSHION ,CARPET AND RELATED PARTS	New	150.00	80.00
5	TO REMOVE ,REPLACE REAR EXHAUST PIPE	New	80.00	0.00
6	TO KNOCK OUT DENTS ,CUT /WELD REAR PANEL ,REMOVE REPLACE ACCIDENT PARTS	New	800.00	580.00
7	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	900.00	680.00
Gross Labour Cost (\$)			2,140.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >