

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22009311/Rvy3m4 8 SHENTON WAY #24-01 AXA TOWER Date: 27/09/2022 SINGAPORE 068811 ATTN: LOW GARNET Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SH 6652L Veh. Inspected SMN 1470S Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M04BAU Excess (\$) 0.00 **LOW GARNET Assign Date** 21/09/2022 Assign From **Vehicle Particulars & Condition** 2. AUDI A3 SEDAN 1.4 TFSI Make & Model 1395 C.C (AMB) Year of Reg. Engine No. **HIDDEN** 2014 Chassis No. WAUZZZ8V4E1028223 Colour **GREY** 123314 KM IN ORDER Odometer Steering **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 225/40 ZR18 MICHELIN 6 mm R/H Front Tyre 225/40 ZR18 MICHELIN L/H Front Tyre 6 mm R/H Rear Tyre 225/40 ZR18 **MICHELIN** 6 mm 225/40 ZR18 **MICHELIN** L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. **General Information Accident Date** 16/09/2022 Inspect Date / Time 22/09/2022 (02:03 PM) Block 7 #01-92 Sin Ming Industrial Estate Sector C Survey held at V8 MOTOR WERKZ PTE LTD

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/ASM22009311/Rvy3m4

Inspected By

Repairer

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser