

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III22009312/TRQY3E2**Date:** 14/02/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747_01
Claimant Vehicle No : GBE3696Y **Insured Vehicle No :** SNG1541X
 Date of Loss: 17/09/2022 Nature of Claim: TP Claim No: MFL2022D0005296

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE3696Y**
 Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Engine No: ZD30346289K
 EURO 5 (A)
 Reg. Date: 17/11/2015 (Man. Year: 2015) Chassis No: JN1SC2F24Z0857911
 Colour: Silver Odometer: 318045 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R13 (D)
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,448.27	3,188.46	3,259.81	50.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	600.00	800.00	57.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,848.27	3,788.46	4,059.81	51.73
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	7,848.27	3,000.00	4,848.27	61.78

INSPECTION

Date of Assignment: 21/09/2022
 Date Inspected: 26/10/2022 Inspected At: Eng Shing Mechanical Works (HQ)
 160 Sin Ming Drive, #06-21 Sin Ming Autocity
 Singapore 575722
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Feb 2023)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE3696Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHR WHEEL GUARD (FRT)	Dented	220.30 FN	*209.40 FN
2	1		*LH SLIDING DOOR (FRT)	Dented	1,400.00 FS	*1,000.00 FS
3	1		*LH SLIDING DOOR (RR)	Repair	1,400.00 FS	*- FS
4	1		*LH SLIDING DOOR RAIL	Repair	650.00 FS	*- FS
5	1		*SET REAR BOX STICKER (CUSTOMISED)	Necessary	2,800.00 FS	*2,000.00 FS
					Sub Total (\$\$)	6,470.30
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	22.03
					Total Parts (\$\$)	3,209.40
						3,188.46

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHTINGS & WIRINGS	New	50.00	0.00
2	TO REMOVE AND RENEW REAR BOX VINYL WRAP	New	250.00	100.00
3	TO REMOVE AND RENEW DAMAGED PARTS. RE-ALIGN ALL AFFECTED AREA	New	600.00	300.00
4	TO PUTTY AND RESPRAY ALL DAMAGED PARTS. TOUCH UP ALL AFFECTED AREA	New	500.00	200.00
Gross Labour Cost (\$\$)			1,400.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >