



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 3664L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	2,500.00	-
1	REAR BOOT	TO REPAIR SEE LABOUR	3,200.00	-
	LESS 10% DISCOUNT		-570.00	-
			5,130.00	-
	<u>SPECIAL NETT ITEMS</u>			
1	WRAPPING (SN)	CUT	1,800.00	600.00
1	CLIPS , SCREW & RIVETS (SN)	NOT NECESSARY	100.00	-
			1,900.00	600.00
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		1,800.00	450.00
	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTION. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BOOT.		1,500.00	400.00
	TO CHECK LIGHTING SYSTEM , WIRING & REWIRE.	NOT NECESSARY	150.00	-
	TO REMOVE AND REINSTALL TAILGATE COMPONENTS.	NOT NECESSARY	220.00	-
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY.	NOT NECESSARY	280.00	-
	TO REMOVE & REINSTALL SENSORS.		200.00	40.00
			4,150.00	890.00
GRAND TOTAL			11,180.00	1,490.00
RECOMMENDED COST OF REPAIRS				1,490.00

Report Ref No. CS/AGI22009318/Gcy3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.